

## **O-Ring Basics** EVERYTHING ABOUT O-RING SEALS



# For our customers' advantage

#### The world's largest O-ring warehouse

COG is your independent manufacturer and leading supplier of precision O-rings and elastomer seals. As an owner-managed family business now in its fifth generation, we draw on more than 150 years' expertise. Because only with in-depth knowledge of the subject can we respond to our customers' complex requirements – and satisfy you with our solutions.

Our dialogue with you forms our central focus. Your wishes and challenges provide our impetus. At the same time, our experience in the development and manufacture of materials forms the basis for being able to offer you proven products in dependable high quality – And at the same time to notch up innovations that set new standards for your sector.

More than 250 employees are committed to this objective, monitoring the market and tackling relevant topics, in order to be able to rapidly react to new challenges with solutions-based approaches. In addition, delivery capability and flexibility are of highest importance. We serve our customers from the world's largest O-ring warehouse. The manufacture of the smallest series also forms part of our service, in order to realise the perfect product for your requirements.

There's always lots involved. We will assist in your success. And delight you with our unparalleled expertise.

2101

Jan Metzger Managing Director

Ingo Metzger Managing Director





#### COG at a glance

- Founded in 1867 in Pinneberg, near Hamburg
- Independent family business employing over 250 staff
- World's largest O-ring warehouse (over 45,000 items kept in stock for immediate delivery)
- State of the art logistics centre for maximum delivery capability
- Quality management to DIN EN ISO 9001
- Environmental management to DIN EN ISO 14001
- Close cooperation with leading manufacturers of raw materials

- Our own mixing and compound development facilities
- Tools available for over 23,000 different O-ring dimensions
- Our own toolshop
- Approvals/certifications for a wide variety of materials, including among others DVGW, NORSOK Standard M-710, ISO 23936-2, BAM, FDA, USP, 3-A Sanitary Standard, BfR, Elastomer Guideline, NSF/ANSI and many more

## CONTENT

General (description, materials)	4
Rubber nomenclature	6
Rubber and its trade names	7
O-ring function	8
Hardness	9
Pressure loading (O-ring behaviour under pressure)	10
Thermal characteristics	11
Media resistance	12
Groove geometry for installation spaces	
(groove depth and width)	13
Definition of installation types	14
Piston seal	15
Rod seal	18
Flange seal	20
Trapezoidal groove	

Triangular groove	23
O-ring installation types	24
Surface roughness	25
Installation spaces for PTFE O-rings	26
Installation spaces for FEP- and PFA-coated O-rings	27
Back-up rings	
Endless vulcanisation	
Surface treatment	
O-Ring storage	
Chemical resistance list	
Certifications / Approvals	46
ISO 3601:2008	48
Permissible deviations	
Index of key words	

## General

An O-ring seal is a means of preventing unwanted leakage or loss of fluid or gas (i. e. media generally).

The O-ring is the most popular form of seal as it is simple to install and needs little installation space. Given correct grooving and material choice, the seal can be used for a very long time within the rubber's temperature limits both as a fixed and as a moving part.

#### Description

An O-ring is a closed circle usually made of flexible rubber (elastomer). The dimensions are defined by the inside diameter  $d_1$  and the cross-section  $d_2$ .



O-ring-sizing

O-rings are gaplessly and seamlessly made of various types of caoutchouc in heated injection or press moulds by vulcanisation (cross-linking).

#### Manufacturing processes

Generally there are two different manufacturing processes for the production of elastomer O-rings possible.

- Compression moulding process (Compression moulding = CM process)
- Injection moulding process (Injection moulding = IM process)

In CM the slug is manually inserted in the tool (mould) before the two mould halves consisting of an upper and a lower part are closed. As this process is very time-consuming, it is primarily suitable for manufacturing smaller quantities and larger dimensions.



Open mould

Compression process

Closed mould

In IM the slug is automatically injected into the tool, which contains several O-ring cavities. This process is particularly suitable for large quantities and small dimensions.



Injection process

#### Elastomers / rubber

Elastomers are polymers whose macromolecules have been linked with one another to form a network with cross-connections. As a result they show the typical rubbery and elastic properties. The raw, non-networked product is called rubber (caoutchouc), and is either obtained from plants that yield the substance or produced synthetically.



Picture of rubber (caoutchouc) macromolecules

Vulcanisation results in the networking of the macromolecules – that is to say, the formation of chemical cross-links between the polymer chains. This has the effect that following the termination of an enforced change of form, elastomers will return to their original shape.



Picture of rubber macromolecules (cross-linked)

#### Materials

Technical rubber materials are structured on the basis of a formula. In terms of chemical resistance, the polymer is the weakest link of the different constituent components as compared with the media to be sealed off.

The choice of the right sealing material is often hence restricted to basic polymer(s). In practice, other influences, such as the type of cross-linking, the quantity of softener(s) used and the type of filler employed may be of significance due to the recipe used. Polymer tolerability alone is hence no guarantee of a reliable seal but is a major precondition.

Ingredient	Quantity in phr	Contingent in %
Rubber (polymer)	100.0	39.0
Filler materials (soot)	90.0	35.1
Softener (mineral oil)	50.0	19.4
Processing aids	3.0	1.2
Ageing prevention media	4.0	1.5
Cross-linking media (sulphur)	2.0	0.8
Activator (organic product)	1.7	0.7
Dispersant (stearic acid)	2.0	0.8
Cross-linking activator (zinc oxide)	4.0	1.5
Total	256.7	100.0

Constituent components of a sample formula for NBR rubber



The components of a formula are generally given in phr (parts per hundred rubber). This is the number of parts of filler material in relation to 100 parts of rubber (polymer).



## **Rubber nomenclature**

The synthesis rubbers are classified per **ISO 1629** or **ASTM D 1418**.

Rubbers in solid form are classified in the following groups according to the chemical composition of their polymer chain:

Group	Chemical name	DIN ISO 1629	ASTM D 1418	COG no.
М	Polyacrylate rubber	ACM	ACM	AC
М	Chlorpolyethylene rubber	CM	СМ	
М	Ethylene acrylate rubber	AEM	AEM	
М	Chlorsulphurated-polyethylene rubber	CSM	CSM	
М	Ethylene-propylene rubber	EPM	EPM	EP
М	Ethylene-propylene-(dien) rubber	EPDM	EPDM	AP
М	Fluoride rubber	FKM	FKM	BF HF LT Vi
		FEPM	FEPM	AF Vi
М	Perfluor rubber	FFKM	FFKM	COG Resist®
0	Epichlorhydrine rubber	СО	СО	
0	Epichlorhydrine-copolymer rubber	ECO	ECO	
0	Propylenoxide-copolymer rubber	GPO	GPO	
R	Butadine rubber	BR	BR	
R	Chloroprene rubber	CR	CR	NE
R	Isobutene-isopropene rubber	IIR	IIR	BT
R	Isopropene rubber	IR	IR	
R	AcryInitrile-butadine rubber	NBR	NBR	P
R	Hydrated acrylnitrile-butadiene rubber	HNBR	HNBR	HNBR
R	Natural-rubber	NR	NR	К
R	Styrol-butadine rubber	SBR	SBR	
Q	Fluor-vinyl-methyl-silicone rubber	FVMQ	FVMQ	Si FL
Q	Phenyl-methyl-silicone rubber	PMQ	PMQ	
Q	Phenyl-vinyl-methyl-silicone rubber	PVMQ	PVMQ	
Q	Vinyl-methyl rubber	VMQ	VMQ	Si
Q	Methyl-silicone rubber	MQ	MQ	
U	Polyesterurethane rubber	AU	AU	COG VarioPur® PU
U	Polyetherurethane rubber	EU	EU	EU

Overview of the major rubber types with brief designation and COG number

# The most common rubbers with trade names

The table below provides an overview of some selected rubbers from which elastomer sealing materials are made with their abbreviations and a selection of trade names.

Basic rubber	Abbrevation	Trade name (selection)
Acrylnitrile-butadiene rubber	NBR	Perbunan®, Europrene N®, Krynac®
Styrol-butadiene rubber	SBR	Europrene®, Buna-S®
Hydrated acrylnitrile-butadiene rubber	HNBR	Therban®, Zetpol®
Chloroprene rubber	CR	Baypren®, Neoprene®
Acrylate rubber	ACM	Nipol AR®, Hytemp®, Cyanacryl®
Ethylene acrylate rubber	AEM	Vamac®
	FKM	Viton®, Dai-El™, Tecnoflon®
Fluoro rubber	FEPM	Viton® Extreme, Aflas®
Perfluoro rubber	FFKM	COG Resist®, Kalrez®, Chemraz®
Silicone rubber	VMQ	Elastosil®, Silopren®
Fluor-silicone rubber	FVMQ	Silastic®
Polyethane rubber	AU/EU	COG VarioPur®, Urepan®, Adiprene®
Ethylene-propylene-(dien) rubber	EPM, EPDM	Buna EP®, Dutral®, Nordel™
Epichlorhydrine rubber	ECO	Hydrin®
Natural rubber	NR	
Polyisoprene rubber	IR	Natsyn®

## **NOTE**

7

A list of the resistances of different types of rubber can be found on page 33 et seq.



#### Overview of some types of rubber (incomplete list)

COG Resist® is a registered trademark of C. Otto Gehrckens GmbH & Co. KG.

COG VarioPur^{\circledast} is a registered trademark of C. Otto Gehrckens GmbH & Co. KG.

Perbunan<sup>®</sup>, Baypren<sup>®</sup>, Krynac<sup>®</sup>, Therban<sup>®</sup> and Buna<sup>®</sup> EP are registered trademarks of Lanxess Deutschland GmbH.

 ${\it Europrene^{\circledast}}\ N, {\it Europrene^{\circledast}}\ SBR \ and \ Dutral^{\circledast} \ are \ registered \ trademarks \ of \ Polimeri \ Europa \ GmbH.$ 

- Nipol<sup>®</sup>, NipolAR<sup>®</sup>, Zetpol<sup>®</sup>, HyTemp<sup>®</sup> and Hydrin<sup>®</sup> are registered trademarks of Zeon Chemicals L.P.
- $\mathsf{Nordel^{\mathsf{TM}}}$  is a registered trademark of The Dow Chemical Company.
- Elastosil® is a registered trademark of Wacker Chemie GmbH.

 ${\it Silastic}^{\circledast} \ {\it is a registered trademark of Dow Corning GmbH \ Deutschland}.$ 

- Viton®, Vamac® and Kalrez® are registered trademarks of E. I. Du Pont de Nemours and Company.
- Dai-El™ is a registered trademark of Daikin Industries, Ltd.

Tecnoflon® is a registered trademark of Solvay Solexis S.p.A.

Aflas® is a registered trademark of Asahi Glass Co. Ltd.

 ${\it Urepan}^{\circledast} \ {\it is a registered trademark of Rhein Chemie \ GmbH}.$ 

Adipren<sup>®</sup> is a registered trademark of Chemtura Corporation.

 $\label{eq:chemraz} Chemraz^{\circledast} \text{ is a registered trademark of Greene, Tweed \& Co. GmbH.}$ 

 $\mathsf{Cyanacryl}^{\circledast} \text{ is a registered trademark of American Cyanamid Company.}$ 

 $\mathsf{Simriz}^{\circledast}$  is a registered trademark of Carl Freudenberg KG.

 ${\it Silopren}^{\circledast} \ {\it is a registered trademark of Bayer AG}.$ 

 $\mathsf{Natsyn}^{\otimes}$  is a registered trademark of the Goodyear Tyre & Rubber Company.

### How they work

The **seal effect** of the O-ring is created by the elastic deformation of its cross-section (d<sub>2</sub>) in an appropriately designed installation space or slot. This means that the circular cross-section is deformed to become elliptical, which closes the gaps between the contact surfaces and at the ground of the groove. This generates a surface compression which is essential if the insulating effect is to be achieved. The scale of the deformation of the O-ring diameter is essentially dependent on the groove depth t. This deformation is generally stated in the form of a compression percentage, and is shown on diagrams. The compression factor is stated as the percentage by which the cross-section d<sub>2</sub> is reduced when compressed in its installed state. While the compression percentage remains the same, the deformation forces increase as the cross-section (d<sub>2</sub>) increases. To balance this out, as d<sub>a</sub> increases the compression percentage is correspondingly reduced.

If the medium to be sealed is under pressure then additional pressure is exerted on the O-ring, which is beneficial to the seal and increases its effectiveness (surface pressure increases).

The pressure pushes the O-ring against the groove flank opposite the source of the pressure. The seal gap should be as small as possible to prevent the ring from being pressed into it. In radial seals there should be a tolerance pairing of H8/f7, in axial seals H11/h11.

If not, or if higher pressures are anticipated, then the material(s) chosen should ensure maximum possible O-ring hardness. Otherwise the extrusion may occur and the O-ring might be destroyed.



Compressed O-ring in installation space without pressure



Compressed O-ring in installation space under pressure

#### **1** IMPORTANT

The cross-section d<sub>2</sub> must always exceed the depth of the installation space.

## Hardness

Hardness is the resistance of a body to penetration by a harder body of a specific shape at a specific pressure over a specific time.

It is measured in Shore or °IRHD (International Rubber Hardness Degree). Comparable values are determined using standard samples and given in Shore A units. For measurements on finished products °IRHD is usual. Hardness values of finished products deviate from those of standard samples as their thickness, curved surface or values measured at the edges are not comparable and the metrology procedures differ.

Measuring hardness at a cross-section  $\leq$  3 mm is only feasible in °IRHD.

The picture below shows the penetrating body (a pyramid stump) for hardness measurement in Shore A (DIN 53505).



Hardness measurement in Shore A

The picture below shows the penetrating body (a sphere) for hardness measurement in °IRHD (DIN ISO 48 CM).



Hardness measurement in °IRHD

Hardness must be adjusted to e.g. pressure load. The softer the elastomer the easier it is deformed under pressure and pressed into the gap to be sealed. On the other side softer elastomers seal at low pressures and between uneven surfaces due to its greater flexibility.



Hardness is not a quality characteristic but a characteristic that plays a role in sealing.

#### **1** NOTE

With a cross-section of ≤ 1.6mm, measurements of the hardness of the O-ring are no longer meaningful.



## **O-ring behaviour under pressure**

The extrusion angle is largely determined by the gap size g between the parts of the machinery. The clearance depends on process, manufacturing method, tolerances influencing clearance, the breathing of the parts under pressure and so on.

Excessive gaps can cause elastomer destruction by extrusion (gap extrusion).



Extruded O-ring

3.01 - 5

O-rings of 90 Shore A hardness permit slightly larger gaps than standard-O-rings of 70 Shore A. The table of guide values below of gap sizes for standard elastomers are maximum values if the components are centred.

5.01 - 7

over 7.01

	0-	Ring hardness 7	0 Shore A		
Pressure (bar)			Gap g		
≤ 35	0.08	0.09	0.10	0.13	0.15
≤ 70	0.05	0.07	0.08	0.09	0.10
≤ 100	0.03	0.04	0.05	0.07	0.08
	0-	Ring hardness 9	0 Shore A		
Pressure (bar)			Gap g		
≤ 35	0.13	0.15	0.20	0.23	0.25
≤ 70	0.10	0.13	0.15	0.18	0.20
≤ 100	0.07	0.09	0.10	0.13	0.15
≤ <b>1</b> 40	0.05	0.07	0.08	0.09	0.10
≤ 175	0.04	0.05	0.07	0.08	0.09
≤ 210	0.03	0.04	0.05	0.07	0.08
< 350	0.02	0.03	0.03	0.04	0.04

2.01 - 3

up to 2

All measurements in mm.

IMPORTANT Pressure direction The gap should be as small as possible.

Cross-section d

O-ring behaviour under pressure



All data based on experience and solely intended as guidance.

## **Thermal characteristics**

Elastomers display optimal characteristics over a wide temperature range and have a long service life. Depending on the type of rubber used, there are two temperature ranges in which this is not the case.

Below a specific temperature – known as the glass transition temperature – elastomers lose their elasticity and mechanical stress resistance. This process is reversible, i. e. after rewarming the original characteristics return.

The upper temperature limit is determined by the influencing media. Permanently exceeding this upper limit leads to destruction of the elastomer and is irreversible.

## Elastomer operating temperatures

The permissible temperature range depends on the material(s) used. It is important to differentiate between permanent temperature (constant or operating temperature) and temporary temperature (peak temperature).



Extreme thermal stress on an O-ring

#### **i** IMPORTANT

11

The operating temperature depends on the media to be sealed. 100 °C air temperature resistance in an O-ring is hence not the same as 100 °C oil resistance.

## Temperature ranges of various elastomer materials (medium: air)



Operating duration of 1,000 hours

Only achievable with special working materials under certain conditions

## **Elastomer media resistance**

Elastomer resistance to various media is of major significance. Two types of change occur: physical and chemical.

#### Physical processes

These processes primarily lead to volume change (swelling or shrinking) of an elastomer in a medium. An elastomer can soak up a medium and swell causing its technical properties to change (e.g. lowered tear resistance or hardness). This doesn't mean the seal ceases to function.

However, excessive swelling may lead to the instal-

Elastomer shrinkage is due to mixture ingredients (e.g. mineral oil). This may lead to the seal pressure

#### Chemical aggression

Contact between the elastomer and the medium can lead to the destruction of the elastomer by the polymer chain being split. This makes the material hard and brittle and it loses its elastic properties.

Details of chemical resistance can be found either in the materials specifications, the relevant literature or resistance lists (e.g. COG resistance list). Chemical aggression must also be avoided at all costs.



Illustration of chemical aggression on an O-ring



A list of the resistances of different types of rubber can be found on page 33 et seq.

Chemical aggression and physical shrinkage

of an O-ring must

always be avoided.



## IMPORTANT

lation space (groove) being overfilled and the O-ring being mechanically destroyed. Details of swelling values can be found in relevant literature, resistance list or determined with practical experimentation, which is a better option. Please contact us for information.

(e.g. softener) being separated out of the medium becoming too low or non-existent and result in leakage. This must be avoided at all costs.

## **Groove geometry for O-ring installation spaces**

O-rings must be laid in purpose-made grooves if they are to seal properly. These installation spaces are usually made with a rotary chisel in a shaft or drill hole, or with a milling machine in a workpiece. Groove geometry is usually rectangular.

The illustration below shows a typical rectangular groove with dimensions as recommended in the relevant standards.



Illustration of a typical rectangular groove

#### Determining groove depth (t)

The relationship of the O-ring cross-section  $(d_2)$  to the groove depth (t) determines the initial compression. The choice of groove depth depends on its intended use. In **static use** initial compression should be between 15 and 30%. In **dynamic use** a greater groove depth and hence lower compression should be chosen, usually between 6 and 20%.

#### Determining groove width (b)

Groove width (b) is determined by the O-ring crosssection ( $d_2$ ) and the elliptical shape after compression plus a free space in which the medium can enter to guarantee even pressure on the seal.

The main objective when selecting a size for the groove width is to avoid groove overfill. It is therefore usually assumed when designing the groove that the O-ring should fill it by up to 85% so that there is space for expansion (swelling, thermal extension), if needed.



The groove depth has a decisive effect on O-ring pressure.



The groove width needs to be adapted to a possible volume increase of the O-ring.

#### Key:

- t = groove depth
- b = groove width
- h = height of the installation space
- g = size of gap to be sealed
- P = media pressure
- A = opposing surface
- B = groove flank surfaces and groove base
- C = surface of the insertion angle
- $r_1 = radius in the base of the groove$
- $r_2 = radius on the upper edge of the groove$
- z = length of installation angle

## **Definition of installation types**

There are various O-ring installation options. The direction in which an O-ring cross-section deforms depends on whether the ring is installed in axial or radial alignment. A differentiation is also made between radial deformation "external seal" (internal groove, piston seal) and "internal seal" (external groove, rod seal).

Most O-rings are statically stressed seals. If the seal is between machinery parts that move towards to each other then the seal is dynamic. O-rings only present a technically optimal solution for dynamic seals in exceptional cases.

#### O-ring installation types

The seal types for installation purposes are defined as follows:



The groove is on the exterior which is called a rod seal.

There are also specialised installations for specific situations such as

Rod seals / radial sealing

- Trapezoidal grooves
- Triangular grooves

# Radial, static or dynamic installation external seal (piston seal)

The diagram below shows a radial, static or dynamic installation of an O-ring in a piston seal.



Illustration of the installation space in a radial piston seal

**i** NOTE

**IMPORTANT** 

This seal type is

preferable in radial installation.

Further information about piston seals can be found on page 16 and 17.

ו≡ו					
				_	
		-	-	-	

The following table provides more details about the names and installation spaces as well as the O-ring.

Designation	Tolerance	Explanation
d <sub>4</sub>	H8	Drill hole diameter
d <sub>9</sub>	f7	Piston diameter (shaft diameter)
d <sub>3</sub>	h11	Inside diameter of the installation space (groove base diameter)
b	+ 0.25	Width of the O-ring installation space (groove width)
g		Gap size
t		Radial depth of the installation space (groove depth)
r <sub>1</sub>	± 0.1 0.2	Radius in the base of the groove
r <sub>2</sub>	± 0.1	Radius on the upper edge of the groove
Z		Length of installation angle ( > $d_2/2$ ), please see table page 24

#### Piston seal (continued)

The following table shows a selection of installation dimensions dependant on cross-section d<sub>2</sub>.

#### **1** NOTE

Strictly speaking the table values only apply to NBR O-rings with a hardness of 70 Shore A. However, experience shows that they can be used for other materials and hardnesses although the groove depth may need adjusting.

The values are calculated based on a possible swelling of up to 15%. If there is less swelling then the groove width can be reduced accordingly.

			t			
a <sub>2</sub>	D	static	dynamic	<b>r</b> <sub>1</sub>	r <sub>2</sub>	Z <sub>min</sub>
1.00	1.58	0.70	0.75	0.30	0.1	0.62
1.50	2.19	1.05	1.15	0.30	0.1	0.92
1.78	2.53	1.30	1.40	0.30	0.1	1.10
2.00	2.78	1.50	1.60	0.30	0.1	1.15
2.50	3.37	1.90	2.00	0.30	0.1	1.43
2.62	3.51	2.00	2.10	0.30	0.1	1.50
3.00	3.98	2.30	2.40	0.60	0.2	1.53
3.53	4.67	2.70	2.80	0.60	0.2	1.80
4.00	5.23	3.10	3.30	0.60	0.2	2.03
4.50	5.90	3.50	3.80	0.60	0.2	2.28
5.00	6.48	3.90	4.30	0.60	0.2	2.53
5.33	6.86	4.20	4.60	0.60	0.2	2.70
5.50	7.05	4.40	4.80	1.00	0.2	2.83
6.00	7.59	4.80	5.20	1.00	0.2	3.09
6.50	8.17	5.30	5.60	1.00	0.2	3.35
6.99	8.68	5.80	6.00	1.00	0.2	3.60
7.50	9.29	6.30	6.50	1.00	0.2	3.86
8.00	9.88	6.80	7.00	1.00	0.2	4.12
9.00	11.14	7.70	7.90	1.00	0.2	4.64
10.00	12.38	8.60	8.80	1.00	0.2	5.15

O-ring installation sizes in a radial piston seal

All measurements in mm.

**Please note:** the values given in the table are only indications and are intended as approximate guidelines. Users are strongly advised to check these values for every specific situation (e. g. by repeated testing). In particular, the contact with the media to be sealed, the temperature at the time of use and the installation conditions may lead to deviations from the values given above.

#### Determining the inside diameter d<sub>1</sub>

In static or dynamic radial external O-ring seals the inside diameter d<sub>1</sub> must be approximately 1–6 % smaller than the groove base diameter d<sub>3</sub>. This means that the O-ring should be installed slightly stretched.

The diagrams below show the permissible ranges of O-ring compression depending on cross-section  $d_2$ .



The O-ring should be installed slightly stretched.

## Dynamic seal compression

# $\begin{array}{c} VP \\ 30 \\ 25 \\ 20 \\ 15 \\ 10 \\ 5 \\ 0 \\ 1 \\ 2 \\ 3 \\ 4 \\ 5 \\ 6 \\ 7 \\ d_2 \end{array}$

Compression diagram for a hydraulic dynamic application

## Static seal compression



Compression diagram for a hydraulic static application



# Radial, static or dynamic installation, internal seal (rod seal)

The diagram below shows a radial, static or dynamic installation of an O-Ring in a rod seal.



Illustration of the installation space in the case of a static radial rod seal

The following table provides more details about the names and installation spaces as well as the O-ring.

Designation	Tolerance	Explanation
d <sub>10</sub>	H8	Drill hole diameter
d <sub>5</sub>	f7	Rod diameter
d <sub>6</sub>	H11	External diameter of the installation space (groove base diameter)
b	+ 0.25	Width of the O-ring installation space (groove width)
g		Gap size
t		Radial depth of the installation space (groove depth)
r <sub>1</sub>	± 0.1 0.2	Radius in the base of the groove
r <sub>2</sub>	± 0.1	Radius on the upper edge of the groove
Z		Length of installation angle ( > $d_2/2$ ), please see table at page 24

			t			
a <sub>2</sub>	D	static	dynamic	r <sub>1</sub>	r <sub>2</sub>	Z <sub>min</sub>
1.00	1.58	0.70	0.75	0.30	0.1	0.62
1.50	2.19	1.05	1.15	0.30	0.1	0.92
1.78	2.53	1.30	1.40	0.30	0.1	1.10
2.00	2.78	1.50	1.60	0.30	0.1	1.15
2.50	3.37	1.90	2.00	0.30	0.1	1.43
2.62	3.51	2.00	2.10	0.30	0.1	1.50
3.00	3.98	2.30	2.40	0.60	0.2	1.53
3.53	4.67	2.70	2.80	0.60	0.2	1.80
4.00	5.23	3.10	3.30	0.60	0.2	2.03
4.50	5.90	3.50	3.80	0.60	0.2	2.28
5.00	6.48	3.90	4.30	0.60	0.2	2.53
5.33	6.86	4.20	4.60	0.60	0.2	2.70
5.50	7.05	4.40	4.80	1.00	0.2	2.83
6.00	7.59	4.80	5.20	1.00	0.2	3.09
6.50	8.17	5.30	5.60	1.00	0.2	3.35
6.99	8.68	5.80	6.00	1.00	0.2	3.60
7.50	9.29	6.30	6.50	1.00	0.2	3.86
8.00	9.88	6.80	7.00	1.00	0.2	4.12
9.00	11.14	7.70	7.90	1.00	0.2	4.64
10.00	12.38	8.60	8.80	1.00	0.2	5.15

The following table shows a selection of installation dimensions dependant on cross-section  $d_2$ .



Strictly speaking the table values only apply to NBR O-rings with a hardness of 70 Shore A. However, experience shows that they can be used for other materials and hardnesses although the groove depth may need adjusting.

The values are calculated based on a possible swelling of up to 15%. If there is less swelling then the groove width can be reduced accordingly.

O-ring installation sizes in a static or dynamic radial rod seal

All measurements in mm.

**Please note:** the values given in the table are only indications and are intended as approximate guidelines. Users are strongly advised to check these values for every specific situation (e. g. by repeated testing). In particular, the contact with the media to be sealed, the temperature at the time of use and the installation conditions may lead to deviations from the values given above.



Further information about rod seales can be found on page 20.



#### Rod seal (continued)

## Determining the inside diameter d<sub>1</sub>

In the event of a static or dynamic radial internal seal, an O-ring must be chosen whose external diameter  $(d_1 + 2d_2)$  is approximately 1–3% greater than the external diameter of the installation space  $d_6$ . This means that the O-ring is fitted so that it is slightly compressed. The inside diameter  $d_1$  must always be  $\geq$  the rod diameter  $d_5$ .

The diagrams below show the permissible ranges of the O-ring compression depending on cross-section  $d_2$ .

#### **1** IMPORTANT

The O-ring should be installed slightly compressed.





#### Static seal compression



## Axial, static installation (flange seal)

The diagram below shows the installation space in axial flange seals.

The following table provides more details about the names and installation spaces as well as the O-ring.

$ \begin{array}{c c} & & & & & & & \\ & & & & & & & \\ \hline & & & &$	

Designation	Tolerance	Explanation
d <sub>7</sub>	H11	External axial diameter
d <sub>8</sub>	h11	Internal axial diameter
b <sub>4</sub>	+ 0.20	With of the O-ring installation space (groove width)
t	+ 0.1	Radial depth of the installation space (groove depth)
r <sub>1</sub>	± 0.1 0.2	Radius in the base of the groove
r <sub>2</sub>	± 0.1	Radius on the upper edge of the groove

d <sub>2</sub>	b <sub>4</sub>	t	r <sub>1</sub>	r <sub>2</sub>
1.00	1.90	0.70	0.30	0.1
1.50	2.80	1.10	0.30	0.1
1.78	3.20	1.30	0.30	0.1
2.00	3.40	1.50	0.30	0.1
2.50	3.90	1.90	0.30	0.1
2.62	4.00	2.00	0.30	0.1
3.00	4.60	2.30	0.60	0.2
3.53	5.30	2.70	0.60	0.2
4.00	6.00	3.10	0.60	0.2
4.50	6.50	3.50	0.60	0.2
5.00	7.40	3.90	0.60	0.2
5.33	7.60	4.20	0.60	0.2
5,50	7.60	4.40	1.00	0.2
6.00	8.00	4.80	1.00	0.2
6.50	8.40	5.30	1.00	0.2
6.99	8.70	5.70	1.00	0.2
7.50	9.50	6.20	1.00	0.2
8.00	9.80	6.70	1.00	0.2
9.00	11.10	7.60	1.00	0.2
10.00	12.20	8.60	1.00	0.2

The following table shows a selection of installation dimensions dependant on cross-section  $\rm d_{2}.$ 



Strictly speaking the table values only apply to NBR O-rings with a hardness of 70 Shore A. However, experience shows that they can be used for other materials and hardnesses although the groove depth may need adjusting.

The values are calculated based on a possible swelling of up to 15%. If there is less swelling then the groove width can be reduced accordingly.

> In axial static installations the pressure direction should be considered when selecting the O-ring.

O-ring installation dimensions in an axial flange seal

All measurements in mm.

**Please note:** the values given in the table are only indications and are intended as approximate guidelines. Users are strongly advised to check these values for every specific situation (e. g. by repeated testing). In particular, the contact with the media to be sealed, the temperature at the time of use and the installation conditions may lead to deviations from the values given above.



Further information about flange seals can be found on page 22.



h

r<sub>2</sub>

Flange seal - internal pressure

#### Flange seal (continued)

#### Determining inside diameter given internal pressure

In installations with internal pressure the external diameter of the O-ring  $(d_1 + 2d_2)$  should be on a par with the external groove diameter  $d_7$ . This means that the O-rings are installed slightly compressed and should hence have a similar external diameter to that of the installation space  $d_7$ .

 $b_4$ 

ød,

internal pressure

#### Determining inside diameter given external pressure

In installations with external pressure the inside diameter d<sub>1</sub> of the O-ring should be on a par with the internal groove diameter d<sub>8</sub>. This means that the O-rings are installed slightly stretched and should hence have a similar internal diameter to that of the installation space d<sub>8</sub>.



Flange seal – external pressure

The diagram below shows the permissible range of

O-ring compression dependant on the cross-section d<sub>2</sub>.



#### **i** IMPORTANT

Observe pressure direction!

#### Trapezoidal groove

This groove shape is desirable if the O-ring has to be held during maintenance, service or starting and stopping tools and machinery. It can also be considered a form of valve seat seal if gasses or fluids e. g. flow in such a way as to create a vacuum pressing the seal out of the groove. Groove processing here is costly and time-consuming. We therefore recommend its use only with a cross-section of  $d_2 \ge 2.5$  mm.



Illustration of a trapezoidal groove

d <sub>2</sub>	b ± 0.05	t ± 0.05	r <sub>2</sub>	r <sub>1</sub>
2.50	2.30	2.00	0.25	0.40
2.62	2.40	2.10	0.25	0.40
3.00	2.70	2.40	0.25	0.40
3.55	3.20	2.80	0.25	0.80
4.00	3.70	3.10	0.25	0.80
5.00	4.40	4.00	0.25	0.80
5.33	4.80	4.20	0.40	0.80
6.00	5.50	4.80	0.40	0.80
7.00	6.50	5.60	0.40	1.60
8.00	7.50	6.50	0.40	1.60
9.00	8.50	7.20	0.40	1.60
10.00	9.50	8.60	0.40	1.60

#### Trapezoidal groove installation dimensions

All measurements in mm.

Please note: The values given in the table are only indications and are intended as approximate guidelines. Users are **strongly advised** to check these values for every specific situation (e. g. by repeated testing). In particular, the contact with the media to be sealed, the temperature at the time of use and the installation conditions may lead to deviations from the values given above.

#### Triangular groove

This groove shape is used in flange and cover seals. In this type of installation space the O-ring has contact on three sides. However, a defined O-ring contact pressure is not guaranteed. The manufacturing can also present difficulties as the tolerances specified are difficult to meet and the seal function can not always be ensured. The groove offers little space for any swelling of the O-ring.



Illustration of a triangular groove

If this groove shape is unavoidable then the dimensions and tolerances in the following table should be adhered to. The O-ring cross-section  $d_2$  should exceed 3 mm if at all possible.

d <sub>2</sub>	b
1.78	2.40 + 0.10
2.00	2.70 + 0.10
2.50	3.40 + 0.15
2.62	3.50 + 0.15
3.00	4.00 + 0.20
3.53	4.70 + 0.20
4.00	5.40 + 0.20
5.00	6.70 + 0.25
5.33	7.10 + 0.25
6.00	8.00 + 0.30
6.99	9.40 + 0.30
8.00	10.80 + 0.30
8.40	11.30 + 0.30
10.00	13.60 + 0.35

Triangular groove installation dimensions

All measurements in mm.



Groove width (b) in trapezoidal grooves is measured at the edges before deburring. The radius  $r_2$  must be such that the O-ring is not damaged during installation in the groove and there is no gap extrusion at high pressure.

## **O-ring installation types**

#### The primary installation tips at a glance:

- Never pull O-rings over sharp edges
- There must not be any dirt or residue in the groove or on the O-ring
- Avoid any potential confusion with other O-rings (see colour coding if present)
- Never use adhesive on an O-ring (possible hardening)
- Do not go over drill holes
- Whenever possible use installation grease/oil. But the material must be resistance against the grease (e. g. do not use mineral oil/Vaseline with EPDM!)
- Detergents/cleansers must be checked for O-ring compatibility
- Do not use any hard or sharp-edged tools
- Short-term expansion of the O-ring's inside diameter by as much as 20% is permissible for installation purposes

O-rings are very sensitive to sharp edges. All edges over which the O-ring is to be pulled or against which it will press must therefore be rounded or deburred. This is a major condition for safe installation.

#### Installation angles

To avoid O-ring damage during installation installation angles for drill holes and shafts must be considered during the design stage.



Installation angle for piston seals



Installation angle for rod seals

The table below shows the minimum lengths of the installation angle for piston and rod seals dependent on cross-section  $d_2$ .

d <sub>2</sub>	z at 15°	z at 20°
to 1.80	2.5	2.0
1.81 - 2.62	3.0	2.5
2.63 - 3.53	3.5	3.0
3.54 - 5.33	4.0	3.5
5.34 - 7.00	5.0	4.0
over 7.01	6.0	4.5

All measurements in mm.

Minimum installation angle lengths

## **Surface roughness**

Surface specifications depend above all on the product's intended purpose and so no generally valid limiting values for roughness can be given. The table below gives values for surface roughness that cover most possible sealing uses. They are only to be considered as recommendations.

Surface	Pressure	Rz (µm)	Ra (µm)
Groove base (B)	static	6.3	1.6
Groove flanks (B)	static	6.3	1.6
Seal area (A)	static	6.3	1.6
Groove base (B)	dynamic	6.3	1.6
Groove flanks (B)	dynamic	6.3	1.6
Seal area (A)	dynamic	1.6	0.4
Installation angle (C)		6.3	1.6

Surface roughness values

#### Explanations

The central roughness value **Ra** is the arithmetic average of all profile deviation from the centre or reference line. The average roughness depth **Rz** is the arithmetic average of the individual roughnesses (profile heights) of five adjacent individual measurement lengths Z1 to Z5.

The characteristic values **Ra** and **Rz** are normally used when specifying surface roughness in sealing technology. As these are insufficient by themselves the material proportion of the roughness profile **Rmr** should also be determined. The material proportion **Rmr** should be approximately 50 to 70% measured at a section depth  $c = 0.25 \times Rz$ , based on a reference line of C0 = 5%.



Installation space design illustration

## **Installation space for PTFE O-rings**

The installation space design for O-rings made from thermoplastic PTFE material is detailed below.

The following diagram shows the installation space for static axial installation.

r<sub>1</sub>

dimensions identical to the nominal dimensions to be sealed. Installation ought preferably to be in axially easily accessible

PTFE O-rings are closed rings of circular crosssection. Dimensions are characterised by the inside diameter  $d_1$  and the cross-section  $d_2$ .

Illustration of an installation space for PTFE O-rings

PTFE O-rings are not form-compressed but manufactured under tension and differ in this fact from elastomer O-rings. They can hence be made in any size.



Illustration of PTFE O-rings

The following table provides more details about the names and installation spaces as well as the O-ring.

Designation	Explanation
d <sub>1</sub>	O-ring inside diameter
d <sub>2</sub>	Cross-section
b	Width of the O-ring installation space (groove width)
t	Radial depth of the installation space (groove depth)
r <sub>1</sub>	Radius at the base of the installation space

The following table shows a selection of dimensions for groove width (b) and depth (t) dependant on cross-section d<sub>2</sub>.

d <sub>2</sub>	b + 0.1	t + 0.05	r <sub>1</sub>
1.00	1.20	0.85	0.2
1.50	1.70	1.30	0.2
1,80	2.00	1.60	0.4
2.00	2.20	1.80	0.5
2.50	2.80	2.25	0.5
2.65	2.90	2.35	0.6
3.00	3.30	2.70	0.8
3.55	3.90	3.15	1.0
4.00	4.40	3.60	1.0
5.00	5.50	4.50	1.0
5.30	5.90	4.80	1.2
6.00	6.60	5.60	1.2
7.00	7.70	6.30	1.5
8.00	8.80	7.20	1.5

Installation dimensions for PTFE O-rings

grooves.

PTFE O-rings have little elasticity. The O-rings used should hence have

# Installation space for FEP- and PFA-coated O-rings

#### FEP-coated O-rings

FEP-coated O-rings offer the best of both worlds: Very high resistance to the widest range of media and at the same time good elasticity. This is because of these O-rings' two-component system. FEP-coated O-rings have an elastic core made from FKM or silicone (VMQ). The respective elastic core is seamlessly coated all around with a thin covering of FEP. While the O-ring's core provides the necessary elasticity, the FEP coating is resistant to chemical media.

#### PFA-coated O-rings

For the very highest temperatures: As well as FEP coatings, COG also offers PFA coating. PFA possesses virtually the same chemical resistance and the same properties as PTFE. However, PFAcoated O-rings can be used at higher temperatures than FEP-coated O-rings, while their low temperature flexibility is the same.

The following table shows a selection of dimensions for groove width (b) and depth (t) on cross-section  $d_2$ .

#### Installation notes:

When it comes to fitting FEP and PFA-coated O-rings, virtually the same recommendations apply as for standard elastomer O-rings. However, when fitting them, bear in mind that because of their coatings, the O-rings should be subjected to only minimum stretching and compression.

#### Installation spaces for FEP-coated O-rings

$\begin{array}{c} \text{cross-section} \\ \text{d}_2 \end{array}$	groove depth t	groove width b
1.78	1.30	2.30
2.62	2.00	3.40
3.53	2.75	4.50
5.33	4.30	6.90
7.00	5.85	9.10

All measurements in mm.



### **Back-up rings**

Back-up rings are used in conjunction with elastomer O-rings. They protect the O-rings from being destroyed if high pressure occurs or larger gaps must be sealed. The back-up rings are predominantly made from PTFE, as this material has the best properties for the most applications: an enormous temperature range spanning -200 °C to 260 °C, the appropriate hardness and a virtually universal resistance to the majority of media. PTFE's flow properties protect the softer rubber rings from mechanical damage. To do so, the back-up rings are fitted behind the O-ring on the non-pressure side, or, if pressure direction changes, at both sides. When it is under pressure, the back-up ring deforms and therefore bridges the gap that must be sealed.

Depending on the application, the following variants of ISO 3601-4-compliant back-up rings are used:

- Spiral back-up rings, type T1
- Diagonal slit back-up rings, type T2
- Unslit back-up rings, type T3
- Diagonal slit concave back-up rings, type T4
- Unslit concave back-up rings, type T5
- Special variants

#### Why back-up rings are used

Some constructions do not permit the sealing gap to be designed so that it is sufficiently small in relation to the system pressure. In such circumstances, the use of a back-up ring makes sense. O-rings count among a machine's most sensitive components, and must be protected from pressure damage. Without this protection, O-rings can be forced into the sealing gap by extrusion, and destroyed. Leaks then result (see page 10).

## Diagonal slit back-up rings, type T2

Thanks to its slit, this most commonly used type of back-up ring is relatively easy to fit in piston seals or rod seals. They are often used in machine construction.



Picture 1: Diagonal slit back-up rings, type T2

Type T2 diagonal slit back-up rings are used at system pressures of 15 MPa (150 bar) to 20 MPa (200 bar).

#### Unslit back-up rings, type T3

Their geometry is relatively basic. A disadvantage of this design is that split installation spaces are generally required, as installation would otherwise be extremely difficult.



Picture 2: Unslit back-up rings, type T3

Type T3 unslit back-up rings are used at system pressures of > 25 MPa (250 bar) and/or temperatures > 135 °C.

			All me	asuremen	ts in mm.
d <sub>2</sub>	1.78	2.62	3.53	5.33	6.99
b5 ±0.1	1.4	1.4	1.8	1.8	2.6

Back-up ring dimensions based on O-ring cord thicknesses  $d_2$  (types T2 and T3)

## Diagonal slit concave back-up rings, type T4

The concave form of these O-rings has been specially developed to provide O-rings with optimum protection, especially where pulsating pressure is present. Thanks to the slit, they are relatively easy to fit into a piston or rod seal.



Picture 3: Diagonal slit concave back-up rings, type T4

Concave full-type back-up rings are used at system pressures of 15 MPa (150 bar) to 20 MPa (200 bar), and also where there is pulsating pressure.

		All measur	ements in mm.
d <sub>2</sub>	b5±0.1	b7±0.1	R
1.78	1.4	1.7	1.2
2.62	1.4	1.8	1.6
3.53	1.8	2.0	2.0
5.33	1.8	2.8	3.0
6.99	2.6	4.1	4.0

Back-up ring dimensions based on O-ring cord thicknesses d<sub>2</sub>

#### Unslit concave back-up rings, type T5

The function of this variant of back-up ring is essentially the same as that of type T4. Thanks to the concave form of their contact finish, these O-rings maintain their contours to approximately the same degree, and can therefore to some extent provide a dependable seal at extreme pressures. However, this variant is difficult to install. In some cases, a split groove is required.



Picture 4: Unslit concave back-up rings, type T5

From a constructional point of view, the type T1 spiral back-up rings and special variants can be regarded as critical. We recommend a technical application consultation.

#### Positioning the back-up ring

Depending on the pressure supply, the back-up ring must be installed on the non-pressure side. If pressure changes, they must be fitted at both sides. In order to prevent confusion about the installation side, it is also possible to use two back-up rings.



Notes on this figure:



b1 = Groove width without back-up ring b2 = Groove width with one back-up ring b3 = Groove width with two back-up rings a = Pressure comes from one direction (moves in direction of the arrow) b = Pressure can affect the O-ring from

b = Pressure can affect the O-ring from both directions

Picture 5: Positioning the back-up ring in a rod application

The required groove widths b2 and b3 are calculated from the previously determined constructional groove width without back-up ring, plus back-up ring width b5 or double back-up ring width 2 x b5 where 2 back-up rings are used.

## **Endless vulcanisation**

O-rings can be manufactured by various processes, and can have a length of up to 3,000 mm (and also larger if required), with different cord sizes and material qualities.

Endless vulcanisation enables uniform complete vulcanisation of O-rings across their entire diameter. The dimensional tolerance of the O-ring cords and surfaces meets the ISO 3601 standard. The O-rings manufactured in this way correspond to O-rings with smaller dimensions manufactured using conventional techniques. Compared to other processes, uniform vulcanisation ensures there are no weak points on the joints. This enables longer-lasting and considerably higher quality seals in various areas of application, such as for example in the high vacuum range or when used with gaseous media.

Note: The endless vulcanisation process is ideal where more rigorous demands apply, as lower tolerances and the resulting high degree of precision are possible when using this production method.

#### Other procedures:

#### Glue

Glued O-rings are extruded cords whose ends have been joined together using adhesive. The adhesive must be chosen according to the elastomer material used, as well as to operating conditions such as pressure, temperature and the medium being used.

#### Vulcanised joints

O-rings with vulcanised joints are produced by holding the cord ends together in a special device in which the ends are then hot vulcanised with a suitable adhesive mixture.

The disadvantages of these two processes are the inferior physical properties in the seam/glued area and the greater tolerances compared to O-rings produced using endless vulcanisation



## **Surface treatment**

O-rings can be subjected to special surface treatment e. g. to adjust adhesion, reduce friction or simplify installation.

The following benefits may be accrued depending on the individual case and the coating procedure used:

- Better separation
- Assembly simplification
- Anti-adhesion effect
- Friction reduction / reduction of wear and tear
- Silicone and paint cross-linking malfunction prevention
- Improvement in lubrication characteristics
- Stick-slip reduction
- Reduction of breakaway force
- Simplification of automated installation

#### "Labs-free" O-rings

"Labs-free" O-rings are free of substances which cause paint cross-linking malfunctions. Such O-rings are particularly suitable for use in compressed air systems used in painting engineering and above all in the automotive industry. Elastomers may contain substances which cause paint cross-linking to malfunction. The causatory substances can be released into the air or by contact with elastomers and then land on the surface(s) to be painted and cause irregularities. The O-rings intended for this use are hence subjected to a special treatment to ensure they are free of such substances.



Designation	Type of coating	Coating purpose
PTFE-ME	PTFE transparent	Installation simplification
PTFE-FDA	PTFE milky-white	Mounting aid
PTFE transparent	PTFE transparent	Conditionally dynamic use
PTFE-black	PTFE-black	Dynamic use
PTFE-grey	PTFE-grey	Dynamic use
Polysiloxane	Silicon resin	Mounting aid
Siliconise	Silicon oil	Installation simplification
Talcum powder	Talcum powder	Installation simplification
Molycoting	MoS2 powder	Installation simplification
Graphiting	Graphite powder	Installation simplification

Caption: Coating options and their typical uses

## **O-ring storage**

Seals stored for long periods may change their physical characteristics. Such changes may include hardening, softening, cracking and other forms of surface degeneration.

This is due to one or more influences such as deformation, oxygen, light, ozone, heat, damp, oil or solvent. Basic instructions on storage, cleaning and preservation of elastomer seals are laid down in the DIN 7716 and ISO 2230 standards.

ISO 2230 contains advice on storing rubber items. The table below gives the maximum storage periods split into three groups.

Rubber base	Maximum storage period	Extension
BR, NR, IR, SBR, AU, EU	5 years	2 years
NBR, XNBR, HNBR, CO, ECO, CR, IIR, BIIR, CIIR,	7 years	3 years
ACM, CM, CSM, EPM, EPDM, FKM, FFKM, VMQ, PVMQ, FVMQ	10 years	5 years

Elastomer storage periods

Certain conditions must be met when storing rubber products.

#### Heat

Storage temperature for elastomers should preferably be in the +5 °C to +25 °C range. Avoid direct contact with heat sources such as radiators or sunlight.

#### Moisture

Relative humidity should be below 70% in the storage space. Extremely damp or dry conditions should be avoided.

#### Light

Elastomer seals should be protected from light when stored. Direct sunlight and strong artificial light with a UV content in particular are to be avoided. We recommend covering windows in storage spaces with red or orange materials.

#### Oxygen and ozone

If possible elastomers should be packaged or put in airtight containers to protect them from circulating air.

#### Deformation

Elastomers should be stored in an untensioned condition if possible. Large O-rings can be stored coiled to save space. If the inside diameter  $d_1 >$ 300mm, the O-ring may be looped over once (i. e. in a figure of 8). It should never be bent.

## **Chemical resistance list**

This list uses a rating system to show the chemical resistance of various elastomer materials to different operating media. The following data is based on tests and information provided by our suppliers and customers.

Because of the different application conditions and composition of the media, this data must only be regarded as a guide. The data is nonbinding and must be checked on a case-by-case basis. With a view to the safe choice of materials we recommend you carry out resistance tests under the conditions of use. For further information, please refer to our product datasheets or contact our application technology department. All information relates to room temperature unless otherwise stated.

#### The specific data are to be understood as follows:

- A = Elastomer exhibuts no or minimal swelling.
- B = Elastomer exhibits low to moderate swelling
- C = Elastomer exhibits moderate to strong swelling
- D = Not recommended
- = Unknown / Not checked

Α													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
1-chlorine-1-nitro ethane	D	D	D	-	D	D	D	D	D	-	D	А	С
Acetaldehyde	В	А	D	-	С	D	D	В	D	-	D	А	С
Acetamide (acetic acid amide)	D	А	А	А	В	D	D	В	А	А	В	А	А
Acetic acid, 30%	В	А	В	-	А	D	D	А	В	-	В	А	А
Acetic acid, glacial acetic acid	В	А	С	В	D	D	D	В	D	-	С	А	В
Acetic anhydride	В	В	С	D	В	D	D	С	D	В	D	А	С
Acetone	С	А	D	D	С	D	D	С	D	D	D	А	В
Acetophenone	D	А	D	D	D	D	D	D	D	-	D	А	С
Acetyl chloride (acetic acid chloride)	D	D	D	D	D	D	D	С	Α	-	А	А	А
Acetylene (ethyne)	В	А	А	-	В	D	D	В	-	-	А	А	А
Acrylonitrile	D	D	D	D	D	D	D	D	D	-	С	А	С
Adipic acid (E 355)	А	А	А	А	А	-	-	-	А	-	А	А	А
Aluminium acetate (aqueous solution)	А	А	В	-	В	D	D	D	D	-	D	А	С
Aluminium chloride (aqueous solution)	А	А	А	А	А	С	А	В	А	-	А	А	А
Aluminium fluoride (aqueous solution)	В	А	А	А	А	С	-	В	А	-	А	А	А
Aluminium nitrate (aqueous solution)	А	А	А	А	А	С	-	В	-	-	А	А	А
Aluminium phosphate (aqueous solution)	А	А	А	А	А	-	-	А	-	-	А	А	А
Aluminium sulphate (aqueous solution)	А	А	А	А	А	D	D	А	А	-	А	А	A
Ammonia (gaseous, cold)	А	А	А	А	А	С	D	А	D	А	D	А	В
Ammonia (gaseous, hot)	D	В	D	D	В	D	D	А	D	-	D	А	В
Ammonia, anhydrous	D	А	В	В	А	D	D	С	D	-	D	А	В
Ammonium carbonate (aqueous solution)	А	-	D	D	А	D	D	-	-	А	А	А	А
Ammonium chloride (aqueous solution)	А	А	А	А	А	А	-	-	-	-	А	А	А
Ammonium hydroxide (concentrated)	D	А	D	-	А	D	D	A	В	-	В	A	А
Ammonium nitrate (aqueous solution)	С	А	А	А	А	D	В	_	-	А	А	А	A

A													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Ammonium nitrite (aqueous solution)	А	А	А	А	А	-	-	В	-	-	А	А	А
Ammonium persulphate (aqueous solution)	А	А	D	D	А	D	D	-	-	-	А	А	А
Ammonium phosphate (aqueous solution)	А	А	А	-	А	-	-	А	-	-	А	А	А
Ammonium sulphate (aqueous solution)	А	А	А	А	А	А	D	-	-	-	В	А	А
Amyl acetate (acetic acid amyl ester)	D	С	D	D	D	D	D	D	D	-	D	А	В
Amyl alcohol (pentanol)	В	А	В	В	В	D	D	D	А	-	В	А	А
Amyl borate	D	D	А	А	А	-	-	-	-	-	А	А	А
Amyl chlornaphtalene	D	D	D	D	D	D	D	D	В	-	А	А	А
Amyl naphtalene	D	D	D	D	D	D	В	D	А	-	А	А	А
Aniline (aminobenzene)	D	А	D	-	D	D	D	D	С	А	С	А	А
Aniline dye	В	А	D	D	В	D	D	С	В	-	В	А	А
Aniline hydrochloride	В	В	В	-	D	D	D	D	В	-	В	А	А
Animal fat	D	В	А	A	В	А	А	В	А	-	А	А	А
Aqua regia	D	С	D	D	D	D	D	D	С	-	В	А	А
Arsenic acid	В	А	А	А	А	С	С	А	А	-	А	А	А
Arsenic trichloride (aqueous solution)	D	С	А	A	А	-	-	-	-	-	D	А	С
Asphalt	D	D	В	-	В	В	В	D	В	-	А	А	А

#### В

Medium	~	MQ	ßR	ABR	~	_	Σ	ð	ζMQ	E/P	Σ	Ψ	ē.
	ž	Е	Ï	Ŧ	ß	AL	AC	5	Ę	Ë	Ŧ	Ë	E
Banana oil (amyl acetate)	D	С	D	D	D	D	D	D	D	-	D	А	В
Barium chloride (aqueous solution)	А	А	А	А	А	А	А	А	А	-	А	А	А
Barium hydroxide (aqueous solution)	А	А	А	А	А	D	D	А	А	-	А	А	А
Barium sulphate (aqueous solution)	А	А	А	А	А	А	D	А	А	-	А	А	А
Barium sulphide (aqueous solution)	А	А	А	А	А	А	D	А	А	-	А	А	А
Beer	А	А	А	А	А	В	D	А	А	-	А	А	А
Beet sugar liquid	А	А	А	А	В	D	D	А	А	-	А	-	-
Benzaldehyde (artificial bitter almond oil)	D	А	D	D	D	D	D	В	С	В	D	В	С
Benzene	D	D	D	D	D	С	D	D	С	С	А	А	А
Benzine (nitro benzine, ligroin)	D	D	А	-	В	В	А	D	А	-	А	А	А
Benzoic acid (E 210)	D	С	С	-	D	D	С	С	В	-	А	А	А
Benzol sulphonic acid	D	С	D	-	В	D	D	D	В	-	А	В	А
Benzoyl chloride	D	D	D	-	D	-	D	-	В	-	В	А	А
Benzyl alcohol	D	А	D	-	В	D	D	В	В	А	А	А	А
Benzyl benzoate	D	В	D	-	D	-	D	-	А	-	А	А	А
Benzyl chloride	D	D	D	-	D	D	D	D	В	А	А	А	А
Biphenyl (diphenyl, phenylbenzene)	D	D	D	D	D	D	D	D	В	-	А	А	А
Blast furnace gas (furnace gas)	D	D	D	D	D	D	D	А	В	-	А	А	А
Bleach solution	D	А	D	В	D	D	D	В	В	А	А	А	А
Borax solution (disodium tetraborat)	В	А	В	А	А	А	В	В	В	-	А	А	А
Bordeaux mixture	В	А	В	-	В	D	D	В	В	-	А	А	-
Boric acid	А	А	А	А	А	А	D	А	А	-	А	А	А
Bromine trifluoride	D	D	D	D	D	D	D	D	D	-	D	В	С
Bromine water	D	В	D	С	D	D	D	D	В	-	А	А	А
Bromine, anhydrous	D	D	D	-	D	D	D	D	В	-	А	А	А
Bromobenzene	D	D	D	D	D	D	D	D	А	-	А	А	А
Bromochloromethane	D	В	D	D	D	D	D	D	В	-	А	А	А
Bunker oil	D	D	А	А	D	В	А	В	А	-	А	А	А
Butadiene	D	С	D	-	D	D	D	D	В	-	A	A	Α

В													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Butane	D	D	А	А	А	А	А	D	А	-	А	А	А
Butter (animal fat)	D	А	А	А	В	А	А	В	А	-	А	А	А
Butyl acetate (acetic acid butylester)	D	С	D	-	D	D	D	D	D	D	D	А	С
Butyl acetylricinoleate	D	А	С	В	В	D	-	-	В	-	А	А	А
Butyl acrylate	D	D	D	D	D	-	D	-	D	-	D	A	С
Butyl alcohol (butanol)	А	В	А	А	А	D	D	В	В	А	А	А	А
Butyl benzoate	С	В	D	-	D	-	D	-	А	-	А	А	А
Butyl ethyl diglycol (CARBITOL)	D	А	D	D	С	-	D	D	D	-	С	A	А
Butyl glycol ether (CELLOSOLVE)	D	А	С	С	С	D	D	-	D	-	D	А	В
Butyl stearate (stearic acid butyl ester)	D	С	В	В	D	-	-	-	В	А	А	А	А
Butylamine	D	В	С	С	D	D	D	D	D	-	D	A	С
Butylene (butene)	D	D	В	D	С	D	D	D	В	-	А	A	А
Butyloleate	D	В	D	D	D	-	-	-	В	-	А	А	А
Butyraldrehyde (butanal)	D	В	D	-	С	D	D	D	D	_	D	В	С

С													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Calcium acetate (aqueous solution)	А	А	В	В	В	D	D	D	D	А	D	А	С
Calcium chloride (aqueous solution)	А	А	А	А	А	А	А	А	А	А	А	А	А
Calcium hydrogen sulphate (aqueous solution)	D	D	D	A	А	А	D	A	A	-	А	А	А
Calcium hydroxide (aqueous solution)	Α	А	А	Α	Α	Α	D	Α	Α	Α	Α	А	А
Calcium hypochlorite (aqueous solution)	С	А	В	В	С	D	D	В	В	А	А	А	А
Calcium nitrate (aqueous solution)	А	А	А	А	А	А	А	В	А	А	А	А	А
Calcium sulphide (aqueous solution)	В	А	А	А	А	А	D	В	А	А	А	А	А
Cane sugar liquid	А	А	А	-	А	D	D	А	А	-	А	А	А
Carbamate	D	В	С	-	В	D	D	-	А	-	А	А	А
Carbitol (ethyl diglycol)	В	В	В	-	В	D	D	В	В	-	В	А	В
Carbolic acid (phenol)	D	В	D	D	С	С	D	D	А	-	А	А	А
Carbon dioxide	В	В	А	А	В	А	-	В	А	-	А	А	А
Carbon disulphide	D	D	С	D	D	-	С	D	А	А	А	А	А
Carbon monoxide	В	А	А	А	В	А	А	А	В	-	А	А	А
Carbon tetrachloride	D	D	С	В	D	D	D	D	С	D	А	В	В
Carbonic acid	А	А	В	А	А	А	А	А	А	-	А	А	А
Castor oil	А	В	А	А	А	А	А	А	А	А	А	А	А
Cellosolve (ethylene glycol ether)	D	В	D	-	D	D	D	D	D	-	С	А	С
Cellosolve acetate (glycol acetate)	D	В	D	D	D	D	D	D	D	-	D	А	С
Chalk sulphur solution	D	А	D	А	А	-	D	А	А	-	А	А	А
Chalk whitener	А	А	А	А	В	-	D	В	А	-	А	А	А
China wood oil (China tung oil)	D	С	А	А	В	С	-	D	В	-	А	А	-
Chlorine dioxide	D	С	D	D	D	D	D	-	В	-	А	А	А
Chlorine trifluoride	D	D	D	D	D	D	D	D	С	-	D	В	С
Chlorine, dry	D	D	D	С	С	D	D	D	А	-	А	А	А
Chlorine, wet	D	С	D	С	С	D	D	D	В	-	В	А	А
Chloroacetic acid	D	А	D	D	D	D	D	-	D	-	D	А	В
Chloroacetone	D	А	D	D	С	D	D	D	D	-	D	А	В
Chlorobenzene	D	D	D	D	D	D	D	D	В	-	A	А	А
Chlorododecane	D	D	D	D	D	D	D	D	A	-	A	А	А
Chloroform (trichloromethane)	D	D	D	D	D	D	D	D	D	D	А	Α	Α

C													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Chloroprene (chlorobutadiene)	D	D	D	D	D	D	D	D	В	-	А	А	А
Chlorosulphic acid	D	D	D	-	D	D	D	D	D	А	D	А	В
Chlorotoluene	D	D	D	D	D	D	D	D	В	-	А	А	А
Chlorox (sodium hypochlorite)	D	В	В	В	А	D	D	В	В	-	А	А	А
Chrome plating solution	D	В	D	D	D	D	D	В	В	-	А	А	-
Chromic acid	D	С	D	D	С	D	D	С	С	А	А	А	А
Citric acid	А	А	А	А	А	А	-	А	А	А	А	А	А
Coal tar (creosote)	D	D	А	-	В	С	А	D	А	-	А	-	-
Cobalt dichloride (aqueous solution)	А	А	А	А	А	D	D	В	А	-	А	А	А
Coconut oil	D	С	А	А	В	В	А	А	А	-	А	А	А
Cod liver oil	D	А	А	А	В	А	А	В	А	-	А	А	-
Coke oven gas	D	D	D	D	D	D	D	В	В	-	А	А	А
Copper acetate (aqueous solution)	А	А	В	В	В	D	D	D	D	-	D	А	С
Copper chloride (aqueous solution)	А	А	А	А	В	А	А	А	А	-	А	А	А
Copper cyanide (aqueous solution)	А	А	А	А	А	А	А	А	А	-	А	А	А
Copper sulphate (aqueous solution)	В	А	А	А	А	А	А	А	А	-	А	А	А
Cotton seed oil	D	В	А	А	В	А	А	А	А	А	А	А	-
Creosote coal tar	D	D	А	А	В	С	А	D	А	-	А	А	А
Cresol (methyl phenol)	D	D	D	-	С	D	D	D	В	А	А	А	А
Cresylic acid	D	D	D	Α	С	D	D	D	В	А	А	А	А
Cumene (isopropylbenzene)	D	D	D	D	D	D	D	D	В	-	А	А	А
Cyclohexane (hexamethylene)	D	D	А	A	С	A	А	D	В	В	А	А	А
Cyclohexanol (hexahydrophenol, anol)	D	С	С	Α	A	-	-	D	А	-	А	А	А
Cyclohexanone (pimelic ketone, anone)	D	В	D	D	D	D	D	D	D	В	D	А	С

Medium	NR	EPDM	NBR	HNBR	СR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Decaline (decahydronaphthalene)	D	D	D	-	D	-	-	D	А	-	А	А	А
Decane	D	D	А	А	D	В	А	В	А	-	А	А	А
Developer fluid (photography)	А	В	А	А	А	-	-	А	А	-	А	А	-
Diacetone	D	А	D	-	D	D	D	D	D	-	D	А	В
Diacetone alcohol	D	А	D	D	В	D	D	В	D	-	D	А	В
Dibenzyl ether	D	В	D	D	С	В	-	-	-	-	D	А	С
Dibenzyl sebacate	D	В	D	D	D	В	D	С	С	-	В	А	А
Dibromethylbenzene	D	D	D	D	D	D	D	D	В	-	В	А	А
Dibutyl ether	D	С	D	D	С	В	С	D	С	-	С	А	В
Dibutyl sebacate (DBS)	D	В	D	D	D	D	D	В	В	-	В	А	А
Dibutylamine	D	С	D	-	D	D	D	С	D	-	D	А	С
Dibutylphthalate (DBP)	D	В	D	D	D	С	D	В	С	-	С	А	А
Dichloro isopropyl ether	D	С	D	D	D	В	С	D	С	-	С	А	В
Dicyclohexylamine	D	D	С	С	D	D	D	-	D	-	D	А	В
Diesel oil	D	D	А	А	С	С	А	D	А	В	А	А	А
Diethyl benzene	D	D	D	-	D	D	-	D	С	-	А	А	А
Diethyl sebacate	D	В	В	С	D	D	D	В	В	-	В	А	А
Diethylamine	В	В	В	-	В	С	D	В	D	-	D	А	В
Diethylene glycol	А	А	А	-	А	D	В	В	А	-	А	А	А
Diisobutylene (isooctene)	D	D	В	А	D	D	D	D	С	-	А	А	А
Diisopropyl ketone	D	A	D	-	D	D	D	D	D	-	D	A	С
Diisopropylbenzene	D	D	D	-	D	-	-	-	В	-	А	A	Α

D													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Diisopropyliden acetone (phoron)	D	С	D	-	D	D	D	D	D	-	D	А	С
Dimethyl ether (methyl ether)	D	D	А	А	С	-	D	А	А	-	D	А	С
Dimethyl formamide (DMF)	D	В	В	-	С	D	D	В	D	А	D	А	В
Dimethyl phthalate (DMP)	D	В	D	D	D	-	D	-	В	-	В	А	А
Dimethylaniline (xylidine, aminoxylole)	С	В	С	-	С	D	D	D	D	-	D	А	В
Dinitrotoluene (DNT)	D	D	D	D	D	D	D	D	D	-	D	А	С
Dioctyl sebacate (DOS)	D	В	D	D	D	В	D	С	С	А	В	А	А
Dioctylphthalate (DOP)	D	В	С	-	D	D	D	С	В	В	В	А	А
Dioxane	D	В	D	D	D	D	D	D	С	D	D	А	С
Dioxolane (glycol methyl ether)	D	В	D	D	D	D	D	D	D	D	D	А	С
Dipentene (paint thinner)	D	D	В	В	D	D	D	D	С	-	А	А	-
Diphenyl (biphenyl, phenylbenzene)	D	D	D	D	D	D	D	D	В	В	А	А	А
Diphenyl oxide	D	D	D	D	D	D	D	С	В	В	А	A	А
Dowtherm oil	D	D	D	D	D	С	D	С	В	_	А	Α	- ,

E													
Medium	NR	EPDM	NBR	HNBR	СК	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Epichlorohydrin	D	В	D	D	D	D	D	D	D	-	D	В	С
Ethane	D	D	А	-	В	С	А	D	В	-	А	А	А
Ethanolamine (aminoethanol) (MEA)	В	В	В	-	В	С	D	В	D	А	D	А	С
Ethyl (ethanethiol)	D	С	D	-	С	-	-	С	-	-	В	А	А
Ethyl acetate (acetic acid ethyl ester)	D	В	D	-	С	D	D	В	D	D	D	А	С
Ethyl acetoacetate	С	В	D	-	С	D	D	В	D	-	D	А	С
Ethyl acrylate	D	В	D	-	D	D	D	В	D	-	D	А	С
Ethyl alcohol	A	Α	А	А	А	D	D	А	А	-	А	А	А
Ethyl alcohol (ethanol)	A	A	A	A	А	D	D	А	А	А	В	А	А
Ethyl benzene	D	D	D	-	D	D	D	D	А	В	А	А	А
Ethyl benzoate	A	A	D	-	D	D	D	D	А	С	А	А	А
Ethyl cellosolve (glycol diethyl ether)	D	D	D	-	D	D	D	D	D	-	D	А	В
Ethyl cellulose	В	В	В	-	В	В	D	С	D	-	D	А	С
Ethyl chloride (chlorethane)	D	С	A	-	D	В	D	D	А	-	А	А	А
Ethyl chlorocarbonate	D	В	D	-	D	D	D	D	В	-	А	А	А
Ethyl chloroformate	D	В	D	-	D	D	D	D	D	-	D	А	-
Ethyl ether (diethyl ether)	D	С	С	-	С	С	D	D	С	-	D	А	С
Ethyl formate (ethyl methanoate)	D	В	D	-	В	-	-	-	А	-	А	В	А
Ethyl oxalate	A	A	D	-	С	A	D	D	В	-	А	А	А
Ethyl pentachlorobenzene	D	D	D	-	D	D	D	D	В	-	А	А	А
Ethyl silicate	В	A	A	-	А	-	-	-	А	-	А	А	А
Ethylendiamene	A	A	A	A	А	D	D	А	D	-	D	В	С
Ethylene (ethene)	С	В	A	-	С	-	-	-	А	-	А	А	А
Ethylene chlorhydrine	В	В	D	-	В	D	D	С	В	А	А	А	А
Ethylene chloride	D	С	D	-	D	D	D	D	С	-	В	А	А
Ethylene glycol (glycol)	A	A	A	A	A	D	С	A	A	-	А	В	А
Ethylene oxide (oxirane, epoxide)	D	С	D	-	D	D	D	D	D	-	D	А	D
Ethylene trichloride	D	С	D	D	D	D	D	D	С	-	A	A	А
Ethyline dichloride (1,2 dichlorethane)	D	С	D	-	D	D	D	D	С	В	А	А	A

F													
Medium	NR	EPDM	NBR	HNBR	СR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Fatty acids	D	С	В	В	В	-	-	С	-	-	А	Α	А
Fish oil (train oil)	D	D	А	-	D	-	-	А	А	-	А	Α	-
Fluorine (liquid)	D	D	D	-	D	D	D	D	-	-	В	В	-
Fluorobenzene	D	D	D	-	D	D	D	D	В	-	А	А	А
Fluoroboric acid	А	А	А	-	A	-	-	-	-	-	-	А	-
Fluorolube	В	А	А	A	В	-	-	А	В	-	В	В	-
Formaldehyde (RT) (methanal)	В	А	С	В	В	D	D	В	D	А	D	А	С
Formic acid (methanoic acid)	В	А	В	-	A	С	-	В	С	В	С	В	С
Freon 11 (trichloromethane)	D	D	В	В	С	D	-	D	В	-	В	В	-
Freon 112	D	D	В	В	С	-	-	D	-	-	В	В	-
Freon 113 (trichlorotrifluoroethane)	С	С	А	A	A	В	-	D	D	-	С	С	С
Freon 114 (dichlorotetrafluoroethane)	А	А	А	A	A	А	-	D	В	-	В	С	-
Freon 114B2	D	D	В	-	С	-	-	D	-	-	В	С	-
Freon 115 (chloropentafluoroethane)	А	А	А	-	A	-	-	-	-	-	В	С	-
Freon 12 (dichlorodifluoromethane)	В	В	А	A	A	А	А	D	С	-	В	В	-
Freon 13 (chlortrifluormethan)	А	А	А	-	A	-	_	D	D	-	В	А	-
Freon 13B1	А	А	А	-	A	А	_	D	-	-	В	В	-
Freon 142b (difluoroethane)	В	В	А	В	A	-	_	-	-	-	D	С	-
Freon 152a (difluoroethane)	А	А	А	-	A	-	-	-	-	-	D	С	-
Freon 21 (dichlorofluoromethane)	D	D	D	-	D	-	_	D	-	-	D	В	-
Freon 218	А	А	А	-	A	-	_	-	-	-	В	-	-
Freon 22 (dichlorofluoromethane)	В	А	D	-	A	D	В	D	D	-	D	В	-
Freon 31	В	А	D	-	В	-	-	-	-	-	D	В	-
Freon 32	А	А	А	-	A	-	_	-	-	-	D	В	-
Freon 502	A	А	В	-	A	-	-	-	-	-	D	С	-
Freon BF	D	D	В	В	С	-	-	D	-	-	В	В	-
Freon C316	А	А	А	-	A	-	-	-	-	-	В	В	_
Freon C318 (octafluorotetraethylene)	A	А	А	A	A	-	-	-	-	-	В	С	-
Freon MF	D	D	А	В	С	С	-	D	-	-	В	-	-
Freon TA	С	В	А	-	В	А	-	С	-	-	D	С	-
Freon TC	D	В	А	-	А	А	-	D	-	-	В	В	-
Freon TF	D	D	А	Α	Α	А	-	D	-	D	В	С	-
Freon TMC	D	С	В	-	С	В	-	С	-	-	В	В	-
Freon T-P35	А	А	А	-	А	А	-	А	-	-	В	В	-
Freon T-WD602	D	В	В	-	В	А	-	D	-	-	В	В	_
Fuel oil	D	D	А	A	В	В	А	D	А	_	А	Α	
Fumaric acid	С	В	А	A	В	_	D	В	А	_	А	A	
Furan	D	С	D	D	D	-	D	_	_	_	D	А	С
Furfural (furfurol)	D	В	D	D	С	С	D	D	-	В	D	В	С
Fyrquel (cellulube)	D	А	D	D	D	D	D	Α	С	_	Α	-	_

G													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Gallic acid	А	В	В	В	В	D	D	-	А	-	А	А	А
Gelatine	А	А	А	-	А	D	D	А	А	-	А	А	А
Generator gas	D	D	А	-	В	А	В	В	В	-	А	Α	А
Glauber salt (aqueous solution)	В	В	D	D	В	-	D	-	А	-	А	А	А
Glucose (dextrose, grape sugar)	А	А	А	А	А	D	-	А	А	-	А	А	А
Glue (DIN 16920)	В	A	A	_	A	A	-	A	A	-	A	_	A

G													
Medium	NR	EPDM	NBR	HNBR	ß	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Glycerine (glycerole, E422)	Α	А	А	-	А	А	С	А	А	А	А	А	А
Glycol (1,2-diol)	A	А	Α	A	A	D	D	А	А	-	А	A	А
Green sulphate broth	В	А	В	В	В	А	В	А	В	-	А	В	-
Н													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Halowax oil	D	D	D	D	D	-	-	D	А	-	А	В	-
Hexafluorosilicic acid	В	В	А	А	В	-	-	D	D	-	А	А	А
Hexane	D	D	А	А	В	В	А	D	А	-	А	А	А
Hexanol	В	С	А	-	В	D	D	В	В	-	А	А	А
Hydraulic oils (mineral oil-based)	D	D	А	А	В	Α	А	С	А	-	А	A	А
Hydrazine (diamide, diazane)	A	А	В	D	В	D	-	С	D	-	D	В	С
Hydrobromic acid	A	А	D	D	D	D	D	D	С	-	А	А	А
Hydrobromic acid (40%)	Α	А	D	-	В	D	D	D	С	-	А	А	А
Hydrochloric acid (cold) 37%	В	А	С	-	В	D	D	С	В	A	А	A	А
Hydrochloric acid (hot) 37%	D	С	D	-	D	D	D	D	С	В	В	А	-
Hydrocyanic acid	В	А	В	В	В	-	D	С	В	-	А	А	А
Hydrofluoric acid, anhydrous	D	С	D	-	D	D	D	D	D	-	D	A	С
Hydrofluoric acid, concentrated (cold)	D	С	D	-	D	С	D	D	D	A	А	А	-
Hydrofluoric acid, concentrated (hot)	D	D	D	-	D	D	D	D	D	-	D	А	С
Hydrogen gas	В	А	А	-	А	А	В	С	С	-	А	А	А
Hydrogen peroxide (90%)	D	В	D	В	D	-	D	В	В	-	В	A	А
Hydrogen sulphide (wet) cold	D	А	D	A	В	_	D	С	С	-	D	A	С
Hydrogen sulphide (wet) hot	D	А	D	D	С	_	D	С	С	-	D	A	С
Hydroquinone	В	В	С	D	D	-	D	-	В	-	В	В	А
Hypochlorous acid	В	В	D	D	D	-	D	-	_	-	A	A	-

Î.													
Medium	NR	EPDM	NBR	HNBR	СR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	
lodine pentafluoride	D	D	D	D	D	D	D	D	D	-	D	В	С
lodoform (triodomethane, antiseptic)	D	D	-	-	D	-	-	-	-	-	С	А	В
i-propylacetate	D	В	D	-	D	D	D	D	D	-	D	А	-
Iron (III) chloride (aqueous solution)	A	A	A	А	А	А	А	В	А	-	А	А	А
Iron (III) nitrate (aqueous solution)	A	A	A	А	А	Α	А	С	А	-	А	А	А
Iron (III) sulphate (aqueous solution)	A	А	А	А	А	А	А	В	А	-	А	А	А
Isobutyl alcohol (isobutanol)	A	А	В	В	А	D	D	А	В	-	А	А	А
Isooctane	D	D	A	А	В	В	А	D	А	В	А	А	А
Isophorone	D	С	D	D	D	С	D	D	D	В	D	А	С
Isopropyl alcohol (isopropanol)	A	A	В	В	В	С	D	А	В	-	А	А	А
lsopropyl chloride	D	D	D	D	D	D	D	D	В	-	А	А	А
Isopropyl ether	D	D	В	В	С	В	С	D	С	D	D	А	С
Isopropylacetate	D	В	D	D	D	D	D	D	D	-	D	А	В
K													
Medium		_		~					γ				

Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Kerosene (lamp kerosene; DIN 51636)	D	D	А	А	В	А	А	D	А	А	А	А	Α

Ĺ													
Medium	NR	EPDM	NBR	HNBR	ß	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Lactic acid (cold)	А	А	А	-	А	-	D	А	А	-	А	А	А
Lactic acid (hot)	D	D	D	-	D	-	D	В	В	-	А	А	А
Lard (animal fat)	D	В	А	А	В	А	А	В	А	-	А	А	-
Lavender oil	D	D	В	В	D	D	В	D	В	-	А	А	А
Lead acetate (aqueous solution)	А	А	В	В	В	D	D	D	D	-	D	А	В
Lead nitrate (aqueous solution)	А	А	А	А	А	-	-	В	А	-	А	А	А
Lead sulphamate (aqueous solution)	В	А	В	-	А	-	D	В	А	-	А	А	-
Ligroin (nitrobenzene)	D	D	А	А	В	В	А	D	А	-	А	А	А
Lindol (hydraulic fluid)	D	А	D	А	D	D	D	С	С	-	В	А	-
Linoleic acid	D	D	В	В	D	-	-	В	-	-	В	А	А
Linseed oil	D	С	А	А	В	В	А	А	А	-	А	А	А
Lubricating oil, petroleum	D	D	A	D	В	В	A	D	A	_	A	A	A
Lye (alkaline solution)	В	А	В	В	В	D	D	В	А	-	В	A	-

М													Ì
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Magnesium chloride (aqueous solution)	А	А	А	А	А	А	А	А	А	А	А	А	А
Magnesium hydroxide (aqueous solution)	В	А	В	В	А	D	D	-	-	-	А	Α	А
Magnesium sulphate (aqueous solution)	В	А	А	-	А	-	D	А	А	-	А	А	А
Maize oil	D	С	А	А	С	А	А	А	А	-	А	А	А
Maleic acid (butenedioic acid)	С	В	D	D	С	-	D	-	-	-	А	А	А
Maleic anhydride (MSA)	С	В	D	D	С	-	D	-	-	-	D	А	В
Malic acid	С	В	А	A	С	-	D	В	А	-	А	А	А
Mercury	Α	Α	Α	A	A	Α	-	-	-	-	Α	Α	Α
Mercury (III) chloride (aqueous solution)	Α	Α	Α	A	A	-	_	_	_		Α	Α	Α
Mesityl oxide	D	В	D	D	D	D	D	D	D	D	D	А	С
Methane	D	D	Α	A	В	С	Α	D	В	-	Α	Α	Α
Methyl acetate (acetic acid methyl ester)	С	Α	D	D	В	D	D	D	D		D	Α	В
Methyl acrylate	D	В	D	-	В	D	D	D	D	-	D	А	С
Methyl alcohol (methanol)	А	А	А	А	A	D	D	А	А	А	D	А	А
Methyl bromide (bromomethane)	D	D	В	В	D	-	_	-	Α		Α	Α	Α
Methyl butyl ketone (propyl acetone)	D	Α	D	D	D	D	D	С	D		D	Α	В
Methyl cellosolve (methylene glycol ether)	D	В	С	С	С	D	D	D	D	A	D	А	В
Methyl chloride (monochloromethane)	D	С	D	D	D	D	D	D	В	-	В	Α	Α
Methyl ether (dimethyl ether)	D	D	А	А	С	-	D	А	А	-	D	А	В
Methyl ethyl ketone (MEK)	D	А	D	-	С	D	D	D	D	D	D	А	В
Methyl formate (methyl methanoate)	D	В	D	D	В	-	_	-	-	-	D	Α	В
Methyl isobutyl ketone (MIBK)	D	В	D	D	D	D	D	D	D	D	D	Α	В
Methyl methacrylate (MMA)	D	С	D	D	D	-	D	D	D	-	D	А	В
Methyl oleate	D	В	D	D	D	-	_	_	В	_	В	Α	Α
Methyl pentane	D	D	D	D	D	D	D	D	В	_	Α	Α	Α
Methyl salicylate (salicyclin acid methyl ester)	С	В	D	-	D	-	_	_	_	с	В	A	A
Methylene chloride (dichloromethane)	D	С	D	-	D	D	D	D	В	В	В	Α	В
Milk	А	Α	Α	Α	A	D	D	А	А	A	А	Α	А
Mineral oil	D	С	Α	A	В	Α	Α	В	Α	A	A	Α	Α
Monochlorobenzene	D	D	D	D	D	D	D	D	В	-	A	Α	Α
Monoethanolamine	В	А	D	-	D	D	D	В	D	-	D	А	В

М													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Monomethyl aniline (MMA)	D	В	D	D	D	D	D	_	-	-	в	А	A
Monomethyl ether	D	D	A	-	С	-	D	А	А	-	D	А	A
Mustard gas	А	А	-	-	А	-	-	А	-	-	А	А	-

N													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Naphtalene	D	D	D	D	D	В	-	D	А	А	А	А	А
Naphtha	D	D	В	В	С	В	В	D	В	-	А	А	А
Naphthenic acid	D	D	В	-	D	-	-	D	А	В	А	А	А
Natural gas	В	D	Α	Α	Α	В	В	А	D	-	Α	Α	А
Neville Winthers acid	D	В	D	D	D	-	D	D	В	-	Α	Α	А
n-hexaldehyde	D	Α	D	_	Α	В	-	В	D	-	D	Α	С
n-hexene-1	D	D	В	В	В	В	Α	D	Α	-	Α	Α	А
Nickel acetate (aqueous solution)	А	Α	В	В	В	D	D	D	D	-	D	Α	В
Nickel chloride (aqueous solution)	А	Α	Α	Α	Α	С	С	А	Α	-	Α	Α	А
Nickel sulphate (aqueous solution)	В	Α	Α	Α	Α	С	D	А	Α	-	Α	Α	Α
Nitirc acid, red fumes	D	D	D	D	D	D	D	D	D	В	С	В	Α
Nitric acid (concentrated)	D	D	D	D	D	D	D	D	С	В	В	Α	Α
Nitric acid (diluted)	D	В	D	_	В	С	D	В	В	В	Α	Α	Α
Nitrobenzene	D	Α	D	D	D	D	D	D	D	Α	В	Α	Α
Nitrobenzene (petroleum ether)	D	D	Α	Α	В	В	Α	D	Α	-	Α	Α	_
Nitroethane	В	В	D	_	С	D	D	D	D	В	D	Α	С
Nitrogen	А	Α	Α	_	Α	Α	Α	А	Α	Α	Α	Α	Α
Nitrogen tetroxicide	D	С	D	D	D	D	D	D	D	-	D	А	С
Nitromethane	В	В	D	D	В	D	D	D	D	-	D	А	С
n-octane	D	D	В	-	В	D	D	D	В	-	Α	А	Α
n-propylacetate (acetic acid propyl ester)	D	В	D	-	D	D	D	D	D	-	D	А	С

0													
Medium	NR	EPDM	NBR	HNBR	cr	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
o-chlornaphtalene	D	D	D	-	D	D	D	D	В	-	А	А	А
Octa chlorotoluene	D	D	D	-	D	D	D	D	В	-	А	А	А
Octa decane	D	D	А	D	В	А	В	D	А	-	А	Α	А
Octyl alcohol (octanol)	В	С	В	В	А	D	D	В	В	-	А	А	А
o-dichlorobenzene	D	D	D	-	D	D	D	D	В	-	А	А	А
Oleic acid	D	D	С	А	С	В	D	D	-	А	В	Α	А
Olive oil	D	В	А	А	В	A	А	С	A	-	А	Α	А
Oxalic acid (ethane diacide, clover acid)	В	А	В	В	В	-	-	В	А	-	А	Α	А
Oxygen, (93–204°C)	D	С	D	D	D	D	D	В	D	-	В	Α	-
Oxygen, cold	В	А	В	D	A	A	В	A	A	-	А	Α	А
Ozone	D	A	D	D	С	A	В	A	В	A	A	A	A

Ρ													
Medium	NR	EPDM	NBR	HNBR	СК	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Paint	D	D	В	В	D	С	D	D	В	-	А	А	А
Paint (cellulose paint)	D	D	D	D	D	D	D	D	D	-	D	А	В
Paint thinner	D	D	D	D	D	D	D	D	D	D	D	А	В
Palmitic acid (n-hexadecanoic acid)	В	В	А	А	В	А	-	D	А	-	А	А	А
Paraffin oil (white oil)	D	D	А	А	В	А	А	D	А	-	А	А	А
p-cymene	D	D	D	-	D	D	D	D	В	-	А	A	А
Peanut oil	D	С	А	-	С	В	А	А	A	-	А	A	-
Perchloric acid	D	В	D	-	В	D	D	D	А	-	А	Α	A
Petroleum gas, liquid (LPG)	D	D	А	А	В	А	С	С	С	-	А	А	А
Petroleum, < 121°C	D	D	А	-	В	В	В	В	В	-	А	А	А
Petroleum, > 121°C	D	D	D	-	В	D	D	D	D	-	В	А	-
Phenol (carbolic acid)	D	В	D	D	С	С	D	D	А	А	А	А	А
Phenylbenzene	D	D	D	D	D	D	D	D	В	-	А	А	А
Phenylethyl ether	D	D	D	D	D	D	D	D	D	-	D	А	В
Phenylhydrazine	А	В	D	-	D	D	D	-	-	-	В	А	В
Phoron (diisopropyliden acetone)	D	С	D	D	D	D	D	D	D	_	D	Α	С
Phosphorus trichloride	D	Α	D	D	D	-	-	-	Α	-	Α	Α	Α
Phosporic acid (20%)	В	Α	В	-	В	Α	_	В	В	_	A	Α	Α
Phosporic acid (45%)	С	Α	D	-	В	Α	_	С	В	Α	A	Α	Α
Pickling solution	D	С	D	-	D	D	D	D	D	-	В	-	Α
Picric acid (2,4,6-trinitrophenol)	В	В	В	-	Α	В	-	D	В	-	Α	Α	Α
Pinene	D	D	В	-	С	В	D	D	В	-	Α	Α	Α
Piperidine (hexahydropyridine)	D	D	D	-	D	D	D	D	D	-	D	Α	С
Plant oil	D	С	Α	Α	С	-	Α	В	Α	-	Α	Α	Α
Plating solution for chrome	D	Α	-	D	D	-	-	D	-	-	Α	Α	Α
Plating solution for other metals	D	Α	Α	Α	D	-	-	D	-	-	Α	Α	Α
Polyvinyl acetate emulsion	В	A	-	-	В	-	-	-	-	-	_	-	-
Potassium acetate (aqueous solution)	A	A	В	-	В	D	D	D	D	Α	D	A	С
Potassium chloride (aqueous solution)	Α	Α	A	A	A	A	Α	Α	A	Α	А	Α	Α
Potassium chromate (aqueous solution)	В	A	A	A	A	В	Α	Α	A	-	A	A	Α
Potassium copper cyanide (aqueous solution)	Α	Α	Α	Α	Α	Α	Α	Α	Α	-	Α	Α	Α
Potassium cyanide (aqueous solution)	A	A	A	A	A	A	A	A	A	-	A	A	Α
Potassium hydroxide (aqueous solution)	В	A	В	В	В	D	D	С	С	A	D	A	Α
Potassium nitrate (aqueous solution)	A	A	A	A	A	A	A	A	A	Α	A	A	Α
Potassium sulphate (aqueous solution)	В	A	A	A	A	A	D	A	A	-	A	A	A
Propane	D	D	A	A	В	С	A	D	В	-	A	A	A
Propyl acetone (methyl butyl ketone)	D	A	D	D	D	D	D	С	D	-	D	A	В
Propyl alcohol (propanol)	A	A	A	A	A	D	D	A	A	A	A	A	A
Propyl nitrate	D	В	D	A	D	-	D	D	D	-	D	A	В
Propyline (propene)	D	D	D	D	D	D	D	D	В	_	A	A	A
Propyline oxide	D	В	D	D	D	D	D	D	D	_	D	A	D
Pyridine	D	В	D	D	D	-	D	D	D	_	D	A	С
Pyroligneous acid	D	В	D	D	В	D	D		D		D		С
Pyrroline	С	С	D	-	D	-	D	В	С	-	D	Α	В

R													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Radiation	С	В	С	С	В	С	С	С	D	-	С	-	С
Rapeseed oil	D	А	В	В	В	В	В	D	A	-	A	A	A
RJ-1 (Mil-F-25558B)	D	D	А	А	В	A	A	D	A	-	A	A	-
RP-1 (Mil-R-25576C)	D	D	А	А	В	А	А	D	А	-	A	А	-

S													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Sal ammoniac (ammonium chloride)	А	А	А	А	А	А	А	В	А	-	А	А	А
Salicyclic acid (2-hydroxybenzoic acid)	А	А	В	В	А	-	-	-	А	-	А	А	А
Salt water	А	А	А	А	В	В	D	А	А	-	А	А	А
Silicate ester	D	D	В	В	Α	Α	-	D	А	-	А	А	А
Silicone grease	А	А	А	А	Α	Α	А	С	А	-	А	А	А
Silicone oil	А	А	А	А	Α	Α	А	С	А	-	А	А	А
Silver nitrate	А	А	В	В	Α	Α	А	А	А	-	А	А	А
Soap solution	В	А	А	A	В	С	D	А	А	-	А	А	А
Soda, crystal water anhydrous	А	А	А	A	А	-	-	А	А	-	А	А	А
Sodium acetate (aqueous solution)	А	А	В	В	В	D	D	D	D	-	D	А	А
Sodium bicarbonate (aqueous solution)	А	А	А	A	А	-	-	А	А	-	А	А	-
Sodium bisulphate (aqueous solution)	А	А	А	A	Α	-	D	A	A	Α	А	-	-
Sodium borate (aqueous solution)	Α	Α	А	А	Α	-	-	Α	Α	Α	Α	Α	А
Sodium chloride (aqueous solution)	А	А	Α	А	Α	Α	-	A	A	Α	A	А	А
Sodium cyanide (aqueous solution)	Α	Α	Α	A	Α	-	-	Α	Α	-	Α	Α	А
Sodium hydroxide (aqueous solution)	Α	Α	В	В	Α	D	С	В	В	Α	В	Α	А
Sodium hypochlorite (aqueous solution)	D	В	В	В	Α	D	D	В	В	Α	A	А	А
Sodium metaphosphate (aqueous solution)	Α	Α	Α	A	В	-	-	-	A	-	Α	Α	А
Sodium nitrate (aqueous solution)	В	Α	В	-	В	-	-	D	-	Α	A	Α	А
Sodium perborate (aqueous solution)	В	Α	В	В	В	-	-	В	A	-	A	Α	А
Sodium peroxide (aqueous solution)	В	Α	В	В	В	D	D	D	A	-	В	Α	А
Sodium phosphate (aqueous solution)	Α	Α	Α	A	В	Α	Α	D	-	Α	Α	Α	А
Sodium silicate (aqueous solution)	А	А	Α	А	Α	-	-	-	-	Α	Α	А	А
Sodium sulphate (aqueous solution)	В	А	A	D	Α	Α	D	Α	Α	Α	A	А	А
Sodium thiosulphate (aqueous solution)	В	А	В	-	Α	Α	D	Α	Α	-	A	А	А
Soya oil (soya bean oil)	D	С	А	A	В	В	A	А	А	-	А	А	А
Stearic acid (octadecanoic acid)	В	В	В	В	В	Α	-	В	-	Α	A	А	А
Styrene, monomer (phenylethylene)	D	D	D	D	D	С	D	D	С	В	В	А	А
Sucrose solution (cane sugar)	А	А	А	В	В	D	D	А	А	-	А	А	-
Sulphite lye	В	В	В	-	В	-	D	D	В	-	А	А	А
Sulphur	D	А	D	D	А	-	D	С	А	-	А	А	А
Sulphur chloride (aqueous solution)	D	D	С	D	С	-	D	С	А	-	А	Α	А
Sulphur dioxide (dry)	В	А	D	D	D	-	D	В	В	В	В	А	А
Sulphur dioxide (liquid under pressure)	D	Α	D	D	D	-	D	В	В	-	В	Α	-
Sulphur dioxide (wet)	D	А	D	D	В	-	D	В	В	-	В	А	А
Sulphur hexafluoride	D	А	В	В	A	-	D	В	В	-	А	В	В
Sulphur trioxide	В	В	D	D	D	-	D	В	В	-	A	А	А
Sulphuric acid (20% oleum)	D	D	D	В	D	D	D	D	D	A	Α	Α	А
Sulphuric acid (concentrated)	D	С	D	-	D	D	D	D	D	A	А	А	А
Sulphuric acid (diluted)	С	В	С	-	В	С	В	D	С	A	А	А	А
Sulphurous acid	В	В	В	В	В	С	D	D	-	-	С	А	в

Т													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Tannic acid (tannin)	А	А	А	A	А	А	D	В	-	-	А	А	А
Tar, bituminous	D	С	В	В	С	-	D	В	А	-	А	А	А
Tartaric acid	С	В	А	А	В	А	-	А	А	-	А	А	А
Terpineol	D	С	В	В	D	В	-	-	А	-	А	А	А
Tetra bromoethane	D	D	D	D	D	-	D	D	В	-	А	А	А
Tetrabromomethane (carbon tetrabromide)	D	D	D	-	D	-	-	D	В	-	А	А	А
Tetrachloroethylene (PER)	D	D	D	D	D	D	D	D	В	D	А	А	А
Tetraethyl lead	D	D	В	В	В	-	-	-	В	-	А	А	А
Tetrahydrofuran (THF)	D	С	D	D	D	С	D	D	D	D	D	А	С
Tetralin (tetrahydronaphthalene)	D	D	D	D	D	-	-	D	А	-	В	А	-
Thionyl chloride (sulphurous acid dichloride)	D	С	D	-	D	D	D	-	-	-	В	А	А
Tin chloride (aqueous solution)	А	А	А	A	А	-	-	В	А	-	A	А	А
Tin tetrachloride (aqueous solution)	А	А	А	A	В	-	-	В	А	-	А	А	А
Titanium tetrachloride	D	D	В	В	D	D	D	D	В	-	А	А	А
Toluene (methyl benzene)	D	D	D	D	D	D	D	D	В	D	В	А	А
Toluene diisocyanate (TDI)	D	В	D	D	D	-	D	D	D	-	D	А	С
Transformer oil	D	D	А	A	В	А	В	В	А	-	А	А	А
Triacetin (glycerin triacetate)	В	А	В	В	В	D	D	-	D	-	D	А	В
Tributoxyethyl phosphate	В	А	D	D	D	D	D	-	В	-	А	А	А
Tributyl mercaptan	D	D	D	-	D	-	D	D	С	-	А	А	А
Tributyl phosphate (TBP)	В	В	D	D	D	D	D	D	D	А	D	А	С
Trichloroacetic acid (TCA)	С	В	В	В	D	D	D	-	D	-	D	А	В
Trichloroethane	D	D	D	D	D	D	D	D	В	-	А	А	А
Trichloroethylene (trichloroethen, tri) (TCE)	D	D	D	С	D	D	D	D	В	D	А	А	А
Tricresyl phosphate (TCP)	D	D	D	D	С	D	D	С	В	А	А	А	А
Triethanolamine (TEA)	В	А	В	С	А	D	D	-	D	А	D	В	С
Triethylaluminium (aluminium triethyl)	D	С	D	-	D	D	D	-	-	-	В	А	А
Triethylborane	D	С	D	-	D	D	D	-	-	-	А	А	А
Trinitrotoluene (TNT)	D	D	D	D	В	-	D	-	В	-	В	А	А
Trioctyl phosphate	D	А	D	-	D	D	D	С	В	-	В	А	А
Tung oil (China wood oil)	D	С	А	Α	В	С		D	В	_	А	А	-
Turbine oil	D	D	В	A	D	А	А	D	В	-	A	А	-
Turpentine	D	D	A	A	D	D	В	D	В	С	A	A	A

U													Ì
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Unsymmetrical dimethylhydrazine	А	А	В	В	В	-	-	D	D	-	D	В	С

V													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Vinegar	В	А	В	В	В	D	D	А	С	-	А	А	A
Vinyl chloride (chloroethylene, chloroethene)	D	D	D	-	D	D	D	-	-	В	А	А	A

W													
Medium	NR	EPDM	NBR	HNBR	ß	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Waste water (in accordance with DIN 4045)	В	В	А	А	В	D	D	В	A	-	А	A	A
Water	А	А	А	А	А	С	D	А	А	А	А	A	A
Water vapour (< 149°C)	D	А	D	D	С	D	D	С	D	А	D	А	-
Water vapour (> 149°C)	D	С	D	D	D	D	D	D	D	-	D	A	-
Whisky and wine	А	А	А	А	А	В	D	А	А	-	А	А	A

X													
Medium	NR	EPDM	NBR	HNBR	CR	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ЕТР
Xylene (xylene, dimethyl benzene)	D	D	D	D	D	D	D	D	А	С	А	А	А
Xylidine (amino xylene, dimethylaniline)	С	В	С	С	С	D	D	D	D	_	D	A	С

Z													
Medium	NR	EPDM	NBR	HNBR	cĸ	AU	ACM	VMQ	FVMQ	TFE/P	FKM	FFKM	ETP
Zeolite	A	A	A	A	A	-	-	-	A	-	A	A	A
Zinc acetate (aqueous solution)	А	А	В	В	В	D	D	D	D	-	D	А	В
Zinc chloride (aqueous solution)	А	А	А	А	А	А	D	А	А	A	A	А	A
Zinc sulphate (aqueous solution)	В	А	А	А	А	-	D	A	A	A	A	A	A



## **Certifications / Approvals** Special requirements to elastomer sealing materials.

Test certificate/ Regulation	Application/Country	Criteria/Standards	Appropriate COG material
<b>ACS approval</b> French Standard NF XP P41-250,Part 1 – 3	Plastic in contact with drinking water Country of origin: France	Testing of formulation based on "Synoptic Documents" – storage test (microbe test)	AP 318, AP 571, AP 372, AP 323, AP 356
<b>BAM test report</b> (Recommendation made by Germany's Bundesanstalt für Materialforschung und -prüfung)	Seals for use in fittings and equipment for gaseous oxygen Country of origin: Germany	Regulation B 7 "oxygen" of the professional association for the chemical industry	Vi 375, BAM, Vi 376, Vi 564, Vi 576, Vi 780
<b>BfR Recommendation</b> (Federal Institute for Risk Assessment)	Plastics in contact with foods Country of origin: Germany	XV recommendation for silicone materials XXI recommendation for nature and synthetic rubbers	Si 50, Si 51, Si 820, Si 840, Si 851 R, Si 870, Si 871, Si 966 B, Si 971 B, Si 972 R, Si 973 R, Si 976 R
<b>DVGW release for gas</b> (German Association for Gas and Water)	Sealing material made of elastomers for gas appliances and gas plants Country of origin: Germany	DIN EN 549	P 549, P 550, P 582, Vi 549, Vi 569, HNBR 702
<b>DVGW release for gas</b> (German Association for Gas and Water))	Sealing material made of elastomers for gas supply lines and gas pipelines Country of origin: Germany	DIN EN 682	P 550, P 682, Vi 569, Vi 682, Vi 840
<b>DVGW</b> release for water (German Association for Gas and Water)	Materials and components for drinking water: Seal materials for drinking water plants Country of origin: Germany	DVGW W 534	AP 318, AP 323, AP 356, AP 360, AP 372, AP 382
DVGW W270 recommendation (German Association for Gas and Water)	Materials in drinking water applications Country of origin: Germany	Microbiologic testing; proliferation of micro- organisms on materials	AP 318, AP 323, AP 324, AP 331, AP 333, AP 356, AP 360, AP 372, AP 382, P 520, P 521, P 582

Test certificate/ Regulation	Application/Country	Criteria/Standards	Appropriate COG material
Elastomer Guideline	Elastomers in contact with drinking water Country of origin: Germany	Guideline for the hygienic evaluation of elastomers in contact with drinking water	AP 318, AP 323, AP 324, AP 330, AP 331, AP 332, AP 333, AP 356, AP 360, AP 372, AP 382, P 520, P 521, P 582
<b>FDA regulation</b> <b>CFR 177.2600</b> (Food and Drug Administration)	Materials for use in food and pharmaceutical industries <i>Country of origin: USA</i>	FDA 21. CFR Part 177.2600 (ingredients, compatibility tests)	AP 302, AP 306, AP 310, AP 311, AP 312, AP 313, AP 315, AP 318, AP 320, AP 323, AP 324, AP 332, AP 333, AP 353, AP 356, AP 360, AP 372, AP 382, COG Resist® RS 75 HS, EP 390, HNBR 410, HNBR 420, HNBR 870, P 300, P 521, P 581, P 581 W, P 582, Si 50, Si 51, Si 60 W, Si 70 W, Si 820, Si 840, Si 851 R, Si 870, Si 871, Si 871 TR, Si 970 FR, Si 973 R, Si 973 TR, Si 973 R, Si 976 TR, Vi 327, Vi 371, Vi 581, Vi 602, Vi 665, Vi 770, Vi 780, Vi 970 W, Vi 971 W
<b>NSF release</b> (National Sanitation Foundation)	Food and sanitary facilities Country of origin: USA	NSF standards and criteria	AP 318, AP 323, AP 324, AP 356, AP 360, AP 372, AP 382, P 520, P 582
<b>USP certification</b> (United States Pharmacopeia, USA)	Use in medical and pharmaceutical industries Country of origin: USA	Varying testing requirements: USP Class I to VII, Chapter 88, USP Chapter 87	AP 302, AP 306, AP 313, AP 315, AP 318, AP 323, AP 324, AP 353, COG Resist <sup>®</sup> RS 75 HS, Si 70 W, Vi 602, Vi 665, Vi 770, Vi 780, Vi 970 W, Vi 971 W
WRAS release (Water Regulations Advisory Scheme)	Plastics in contact with drinking water Country of origin: Great Britain	British Standard BS 6920	AP 318, AP 323, AP 324, AP 331, AP 333, AP 356, AP 360, AP 372, AP 382, P 520, P 521, P 582
<b>3-A Sanitary Standard</b> (3-A Sanitary Standard Inc.)	Materials for use in hygienic dairy and food industry plants <i>Country of origin: USA</i>	3-A Sanitary Standards and criteria, Class I to IV	AP 302, AP 306, AP 315, AP 318, AP 323, AP 324, COG Resist <sup>®</sup> RS 75 HS, P 300, P 581, Vi 780, Vi 970 W, Vi 971 W

The table above only provides a sample of all our certifications and approvals. Extensive up-to-date information can be found at www.cog.de.

## The ISO 3601:2008 standard

The new ISO 3601:2008 standard currently consists of 5 parts:

 ISO 3601-1:2008
 "Inside diameters, cross-sections, tolerances and designation codes"

#### O ISO 3601-2:2008

"Housing dimensions for general applications"

• ISO 3601-3:2008 "Form and surface deviations"

- ISO 3601-4:2008 "Back-up rings"
- ISO 3601-5:2008
  "Specification of elastomeric metarials for industrial applications"

#### The DIN 3771 is no longer valid and has been completely replaced by the ISO 3601 standard.

## Permissible deviations for the inside diameter of O-rings in accordance with ISO 3601:2008

The following table gives an overview of dimensions and permissible tolerances. The exact tolerance levels based on ISO 3601:2008 Class B for O-rings with reference to general industrial applications can be calculated using the following formula:

#### $\Delta d_1 = \pm [(d_1^{0.95} \times 0.009) + 0.11]$

#### Example

Calculation of tolerances on the O-ring 100 mm x 5.33 mm

Inside diameter  $d_1 = 100 \text{ mm}$ 

Cross-section  $d_2 = 5.33 \text{ mm}$ 

Deviation for the inside diameter  $\Delta d_1$  using the following formula

 $\Delta d_1 = \pm [(d_1^{0.95} \times 0.009) + 0.11] = \pm [(100^{0.95} \times 0.009) + 0.11] = \pm 0.825 \text{ mm}$ 

Deviation for the cross-section  $\Delta d_2 = 0.13$  mm according to the table -

cross-section d <sub>2</sub> (mm)	1.02	1.27	1.52	1.78	2.62	3.53	5.33	6.99
permissible deviations ±	0.08	0.08	0.08	0.08	0.09	0.10	0.13	0.15

**Result:** O-ring 100 mm ± 0.825 mm x 5.33 mm ± 0.13 mm

All measurements in mm.

## Permissible deviations for O-ring cross-sections according to ISO 3601:2008

#### For general industrial applications (Size code 001 - 475)

cross-section d <sub>2</sub> (mm)	1.02	1.27	1.52	1.78	2.62	3.53	5.33	6.99
permissible deviations ±	0.08	0.08	0.08	0.08	0.09	0.10	0.13	0.15

All measurements in mm.

#### For general industrial applications (Not standardized O-rings)

cross-section d <sub>2</sub> (mm)	0.80 < d <sub>2</sub> ≤ 2.25	2.25 < d <sub>2</sub> ≤ 3.15	3.15 < d₂ ≤ 4.50	4.50 < d₂ ≤ 6.30	6.30 < d <sub>2</sub> ≤ 8.40
permissible deviations ±	0.08	0.09	0.10	0.13	0.15

All measurements in mm.

## Form and surface deviations for O-rings in accordance with ISO 3601:2008

Type of deviationg	Schematic representation (in cross-section)	Dimensions	>0.8 ≤2.25	>2.25 ≤3.15	>3.15 ≤4.50	>4.50 ≤6.30	>6.30 ≤8.40
Offset and form deviation		e	0.08	0.10	0.13	0.15	0.15
		х	0.10	0.12	0.14	0.16	0.18
Combined, burr		У	0.10	0.12	0.14	0.16	0.18
		а		no moi	re than 0.	07 mm	
Indentation		g	0.18	0.27	0.36	0.53	0.70
		u	0.08	0.08	0.10	0.10	0.13
Deburring area	c c	n	Debu dia	urring ist Imeter n i	allowed if s not grea	f the mini ater than	mum d <sub>2</sub> .
Row lines, radial expansion,		V	1.50	1.50	6.50	6.50	6.50
not permissible		k	0.08	0.08	0.08	0.08	0.08
Recesses,		W	0.60	0.80	1.00	1.30	1.70
indentation points		t	0.08	0.08	0.10	0.10	0.13

All measurements in mm.

## Index of key words

#### А

Application options for coated O-rings	Page 27	Gap extrusion	Page 10
Approvals	Page 46	Gap size	Page 10
ASTM D 1418	Page 6	Groove depth	Page 13
	0	Groove geometry	Page 13

G

Groove width

#### В

Back-up rings

Page 28

#### С

Central roughness value (Ra)
Certifications
Chemical aggression
Chemical resistance list
CM process
Coating options
Compression flange seal
Compression moulding process
Compression piston seal
Compression rod seal

#### D

Determining groove depth
Determining groove width
Determining inside diameter
Dynamic installation

#### Е

Elastomers Elastomer storage Extrusion / gap extrusion

#### F

FEP-coated O-rings Flange seal Form and surface deviations

#### <sup>28</sup> H

#### Hardness Page 9 Hardness measurement Page 9 Housing dimensions for flange seals Page 22 Page 25 Housing dimensions for piston seals Page 15 Page 46 Housing dimensions for rod seals Page 18 Page 12 Page 33 Page 4 I Page 31 Page 22 °IRHD Page 9 Page 4 IM process Page 4 Page 17 Injection moulding process Page 4 Page 20 Inside diamter d Page 17, 20, 22 Installation angles Page 24 Installation dimensions for flange seals Page 21 Installation dimensions for piston seals Page 16 Installation dimensions for rod seals Page 19 Page 13 Installation of FEP- and PFA-coated O-rings Page 27 Page 13 Installation of O-rings Page 24 Page 17, 20, 22 Installation types Page 14 Page 15 Installation type flange seals Page 20 Installation type piston seals Page 15 Installation type rod seals Page 18 Installation spaces Page 13 Installation space for PTFE O-rings Page 26 Page 5 ISO 1629 Page 6 Page 32 ISO 2230 Page 32 Page 10 ISO 3601:2008 standard Page 48

#### L

Page 27 "Labs-free" O-rings Page 20 Page 24

Page 31

Page 13

#### Μ

Macromolecules of rubber Manufacturing processes Media resistance Minimum installation angle lengths Mixture ingredients Mode of action of the O-ring Molycoting

#### Ο

Operating temperatures O-ring description O-ring installation O-ring storage

#### Р

Permissible deviations	Page 49	-
PFA-coated O-rings	Page 27	٦
phr	Page 5	-
Physical processes	Page 12	-
Piston seal	Page 15	
Polysiloxane	Page 31	
Pressure characteristics of O-rings	Page 10	
PTFE coating	Page 26	
PTFE O-rings	Page 26	

#### R

Ra (Central roughness value)	Page	25
Radial installation	Page	15
Rod seal	Page	18
RZ (Roughness depth)	Page	25
Rubber	Page	5
Rubber nomenclature	Page	6
Rubber trade names	Page	7

#### S

Page 5	Sample formula	Page 5
Page 4	Sealing materials	Page 5
Page 12	Sealing effect of the O-ring	Page 8
Page 24	Shrinking	Page 12
Page 5	Shore A	Page 9
Page 8	Siliconise	Page 31
Page 31	Static seal	Page 20
	Storage of O-rings	Page 32
	Surface deviation	Page 49
	Surface pressure	Page 8
	Surface roughness	Page 25
Page 11	Surface treatment	Page 31
Page 4	Swelling	Page 12
Page 24		
Page 32		

#### Т

	Talcum powder	Page 31
	Temperature ranges	Page 11
e 49	Thermal characteristics	Page 11
e 27	Tolerances ISO 3601	Page 48
e 5	Trapezoidal groove	Page 23
e 12	Triangular groove	Page 23
e 15		-



C. Otto Gehrckens GmbH & Co. KG Dichtungstechnik · Seal Technology

Gehrstücken 9 · 25421 Pinneberg · Germany Tel +49 (0)4101 5002-0 Fax +49 (0)4101 5002-83 Mail info@cog.de

www.COG.de

© 2019-02 (O) C. Otto Gehrckens GmbH & Co. KG • Errors and amendments excepted.